

Vehicle Inspection Report

Conducted by Classic Performance Engineering, Bicester

Date Completed 20/01/2022



**CLASSIC
PERFORMANCE
ENGINEERING**

Vehicle Details

Make **Sunbeam** Engine no.
Model **Rapier** Registration **LEB 478**
Chassis no. Recorded Mileage **97,259 miles**

Exterior

Area of Inspection	Comments																																				
Bodywork	As per images, working rally prepped car (Images 1-3)																																				
Brightwork	As per images, working rally prepped car (Images 1-3)																																				
Wheels & Tyres	See images (Images 4-7) <table border="1"><thead><tr><th>Position</th><th>Wheel Cond.</th><th>Original Spec.</th><th>Tyre Cond.</th><th>Size</th><th>Year</th></tr></thead><tbody><tr><td>NSF</td><td>Surface wear</td><td></td><td>Good – Almost new</td><td>185 / 65 R14</td><td>2017/2018</td></tr><tr><td>OSF</td><td>Surface wear</td><td></td><td>“</td><td></td><td>“</td></tr><tr><td>NSR</td><td>Surface wear</td><td></td><td>“</td><td></td><td>“</td></tr><tr><td>OSR</td><td>Surface wear</td><td></td><td>“</td><td></td><td>“</td></tr><tr><td>SPARE</td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Position	Wheel Cond.	Original Spec.	Tyre Cond.	Size	Year	NSF	Surface wear		Good – Almost new	185 / 65 R14	2017/2018	OSF	Surface wear		“		“	NSR	Surface wear		“		“	OSR	Surface wear		“		“	SPARE					
Position	Wheel Cond.	Original Spec.	Tyre Cond.	Size	Year																																
NSF	Surface wear		Good – Almost new	185 / 65 R14	2017/2018																																
OSF	Surface wear		“		“																																
NSR	Surface wear		“		“																																
OSR	Surface wear		“		“																																
SPARE																																					
Glass	OK																																				
Lights	Main lights front and back OK Sidelights permanently on Main roof lamp inop Right hand spot lamp inop																																				

For
HANGAR136

Vehicle Inspection Report

(Continued)



CLASSIC
PERFORMANCE
ENGINEERING

Interior

Area of Inspection	Comments
Cosmetic/Trim	Working rally prepped car, see images (Images 8-9)
Function	All switches work as they should (Images 10)

Underside

Area of Inspection	Comments
Chassis	Surface rust, would recommend clean and wax oil
Front/Rear Suspension	Rear leaf springs getting flat / lack of positive suspension Both trunnions have slight play
Drivetrain	All OK Slight play in rear wheel bearing
Exhaust System	Slight blowing from rear silencer Rubber exhaust hangers are perished
Brake System	Can feel slight sticking on the left hand front brake calliper on ramp inspection All other braking systems look OK on visual inspection Hand brake works well

Engine Bay

Area of Inspection	Comments
	Engine condition as per images, (Images 11)

For

HANGAR136

Vehicle Inspection Report

(Continued)



CLASSIC
PERFORMANCE
ENGINEERING

General View	Slight oil leaks in keeping with age and vehicle use, Have cleaned underside of gearbox to observe oil leak Wiring as per images attached (Images 12-14) Radiator has signs of leaks (Images 15)
---------------------	---

Test Drive Report

Area of Inspection	Comments
General Notes	Drives well for rally prepped car, Advise oil change, date on filter 23/06/15, oil very dark on inspection (Images 16)

Vehicle Inspection Report

(Continued)



CLASSIC
PERFORMANCE
ENGINEERING

Photo Evidence

Ref ID

01-03

Image



For

HANGAR136

Vehicle Inspection Report

(Continued)



CLASSIC
PERFORMANCE
ENGINEERING

04-07



08-09



For
HANGAR136

Vehicle Inspection Report

(Continued)



CLASSIC
PERFORMANCE
ENGINEERING

10



11



For
HANGAR136

Vehicle Inspection Report

(Continued)



CLASSIC
PERFORMANCE
ENGINEERING

12-14



14



15



For
HANGAR136

Vehicle Inspection Report

(Continued)



CLASSIC
PERFORMANCE
ENGINEERING

16



For
HANGAR136