

Vehicle Inspection Report

Conducted by Classic Performance Engineering, Bicester

Date Completed 30/03/2022



**CLASSIC
PERFORMANCE
ENGINEERING**

Vehicle Details

Make	Triumph	Engine no.	
Model	TR3	Registration	UOC 784
Chassis no.	846606	Recorded Mileage	57074
Comm no.	TS13498		

Exterior

Area of Inspection	Comments																																				
Bodywork	Good condition, reasonable paint Hard top good Very slight corrosion on edge of boot lid (Photo ID 01)																																				
Brightwork	Only brightwork is rear ¼ bumpers – in good condition																																				
Wheels & Tyres	Wheels are in good condition There is good tread except left rear getting low Spare tyre good condition <table border="1"><thead><tr><th>Position</th><th>Wheel Cond.</th><th>Original Spec.</th><th>Tyre Cond.</th><th>Size</th><th>Year</th></tr></thead><tbody><tr><td>NSF</td><td>✓</td><td>Mini Lite</td><td>✓ Old</td><td>165 R15</td><td>2003</td></tr><tr><td>OSF</td><td>✓</td><td>Mini Lite</td><td>✓ Old</td><td>165 R15</td><td>2003</td></tr><tr><td>NSR</td><td>✓</td><td>Mini Lite</td><td>Low Old</td><td>165 R15</td><td>2003</td></tr><tr><td>OSR</td><td>✓</td><td>Mini Lite</td><td>✓ Old</td><td>165 R15</td><td>2003</td></tr><tr><td>SPARE</td><td>Get you home</td><td></td><td></td><td></td><td></td></tr></tbody></table>	Position	Wheel Cond.	Original Spec.	Tyre Cond.	Size	Year	NSF	✓	Mini Lite	✓ Old	165 R15	2003	OSF	✓	Mini Lite	✓ Old	165 R15	2003	NSR	✓	Mini Lite	Low Old	165 R15	2003	OSR	✓	Mini Lite	✓ Old	165 R15	2003	SPARE	Get you home				
Position	Wheel Cond.	Original Spec.	Tyre Cond.	Size	Year																																
NSF	✓	Mini Lite	✓ Old	165 R15	2003																																
OSF	✓	Mini Lite	✓ Old	165 R15	2003																																
NSR	✓	Mini Lite	Low Old	165 R15	2003																																
OSR	✓	Mini Lite	✓ Old	165 R15	2003																																
SPARE	Get you home																																				

For
HANGAR136

Vehicle Inspection Report

(Continued)



CLASSIC
PERFORMANCE
ENGINEERING

Area of Inspection Glass	Comments Good Perspex side windows, good (a little scratched) Rear screen scratched but serviceable (Photo ID 02)
Area of Inspection Lights	Comments All working Rear rain light not operational/switched

Interior

Area of Inspection Cosmetic/Trim	Comments Trim OK but a little "loose" on seats
Area of Inspection Function	Comments

For

HANGAR136

Vehicle Inspection Report

(Continued)



CLASSIC
PERFORMANCE
ENGINEERING

Underside	
Area of Inspection	Comments
Chassis	Good condition - straight
Front/Rear Suspension	Good condition Bushes good Well lubricated
Drivetrain	All in good order except propshaft which needs U/J's
Exhaust System	Good condition, securely mounted
Brake System	All good, rear brake shoes not checked as required removing rear hubs

For

HANGAR136

Vehicle Inspection Report

(Continued)



CLASSIC
PERFORMANCE
ENGINEERING

Engine Bay

Area of Inspection	Comments
General View	Generally good Wiring could be tidier but functional

Test Drive Report

Area of Inspection	Comments
General Notes	Choke/cold start poor – choke needs adjusting Initial “pick-up” on throttle poor – needs carb set up Hardtop rattles – mounts need checking Brakes good Steering good

For

HANGAR136

Vehicle Inspection Report

(Continued)



CLASSIC
PERFORMANCE
ENGINEERING

Recommendations:

- Attend to choke linkage
- Tighten hard-top mounts
- Attend to carb set up
- Replace propshaft

Adjusted/Remedied:

- N/S brake light not working. Feed wire into bullet connector just pushed in. New connector fitted. Cleaned up earth.
- Choke linkage cable tightened – now allows choke to partially operate but needs fully sorting.
- Fuel banjo bolts tightened.
- Compression test carried out:
 1. 110
 2. 120
 3. 110
 4. 110

For
HANGAR136

Vehicle Inspection Report

(Continued)



CLASSIC
PERFORMANCE
ENGINEERING

Photo Evidence

Ref ID

01

Image



02



For
HANGAR136