

# Free Pre-Delivery Inspection

Milcars (Temple Fortune) Ltd  
Tel 0181-455 4466  
Dealer No 16347



8/9/99  
Date

*[Signature]*  
Stamp/Signature

BMW Oil Service

7955 miles

Milcars (Temple Fortune) Ltd  
Tel 020-8455 4468  
Dealer No 16347



21/8/00  
Date/Stamp/Signature

BMW Oil Service

25265 miles

Ocean Torbay  
Tel 01803-558567  
Dealer No 16337



12-6-03  
Date/Stamp/Signature

# Free Running-in Service at 1200 miles M3 Only

at \_\_\_\_\_ (miles)

Date

Stamp/Signature

BMW Inspection I

14787 miles

Milcars (Temple Fortune) Ltd  
Tel 020-8455 4466  
Dealer No 16347



9/8/01  
Date/Stamp/Signature

BMW Inspection II

~~SALES SERVICE MOT~~

ALAN KERR LTD  
BRIXHAM ROAD  
PAIGNTON  
DEVON TQ4 7BG  
TELE: 01803 556234  
\_\_\_\_\_ miles

10/1/05  
Date/Stamp/Signature

~~BMW Oil Service~~

~~34,325~~ miles

~~Westerly No 16295  
Barnstaple  
Tel: 01271 325444 BMW Service~~

~~13.9.05~~  
Date/Stamp/Signature

BMW Oil Service

\_\_\_\_\_ miles

\_\_\_\_\_

Date/Stamp/Signature

BMW Oil Service

39,903 miles

Westerly No 16295  
Barnstaple  
Tel: 01271 325444 BMW Service

7.8.06  
Date/Stamp/Signature

BMW Oil Service

54759 miles

PADDOCK MOTORS  
EXETER  
BMW SPECIALIST  
01404 851021

5/12/08 *MJE*  
Date/Stamp/Signature

BMW Inspection I

\_\_\_\_\_ miles

\_\_\_\_\_

Date/Stamp/Signature

BMW Inspection II

34,325 miles

Westerly No 16295  
Barnstaple  
Tel: 01271 325444 BMW Service

13.9.05  
Date/Stamp/Signature

BMW Inspection I

47,546 miles

Westerly No 16295  
Barnstaple  
Tel: 01271 325444 BMW Service

25.6.07 *[Signature]*  
Date/Stamp/Signature

BMW Inspection II

63,042 miles

PADDOCK MOTORS  
EXETER  
BMW SPECIALIST  
01404 851021

23/7/10 *[Signature]*  
Date/Stamp/Signature



BMW Oil Service

70588 miles

Westerly Exeter  
BMW Service  
Authorized Workshop  
Tel: 01392 822540  
Dealer No. 16248

17/9/12 *[Signature]*

Date/Stamp/Signature

BMW Oil Service

81750 miles

Westerly No 16295  
Barnstaple  
Tel: 01271 325444 BMW Service

20.4.16 *[Signature]*

Date/Stamp/Signature

BMW Oil Service

83969 miles

BRAKE FLUID CHANGE

BOSCH Service

A & K Gifford  
Tel: 01409 259408

15.6.22 *[Signature]*

Date/Stamp/Signature

BMW Oil Service

84522 miles

PADDOCK MOTORS  
BMW & MINI SPECIALIST  
01395 232049

20-09-2023 *[Signature]*

Date/Stamp/Signature

BMW Inspection I

76331 miles

PADDOCK MOTORS  
BMW & MINI SPECIALIST  
01395 232049

15.07.14 - *[Signature]*

Date/Stamp/Signature

BMW Inspection II

82918 miles

PADDOCK MOTORS  
BMW & MINI SPECIALIST  
01395 232049

04.05.18 *[Signature]*

Date/Stamp/Signature

BMW Inspection I

\_\_\_\_\_ miles

\_\_\_\_\_

Date/Stamp/Signature

BMW Inspection II

\_\_\_\_\_ miles

\_\_\_\_\_

Date/Stamp/Signature



Brake fluid changed   
 Coolant changed   
 Extinguisher checked   
 Extinguisher recharged   
 Microfilter changed

**BMW**  
 Gower Turbay  
 Tel: 01503 558517  
 Dealer No 16337

25265 miles

12-6-03 *[Signature]*

Date/Stamp/Signature

Brake fluid changed   
 Coolant changed   
 Extinguisher checked   
 Extinguisher recharged   
 Microfilter changed

Westerly No 16295  
 Barnstable

47546 miles

25-6-07 *[Signature]*

Date/Stamp/Signature

Brake fluid changed   
 Coolant changed   
 Extinguisher checked   
 Extinguisher recharged   
 Microfilter changed

Westerly No 16295  
 Barnstable

74337 miles

14/11/2013 *[Signature]*

Date/Stamp/Signature

Brake fluid changed   
 Coolant changed   
 Extinguisher checked   
 Extinguisher recharged   
 Microfilter changed

Westerly No 16295  
 Barnstable  
 BMW Service

34325 miles

14-9-05 *[Signature]*

Date/Stamp/Signature

Brake fluid changed   
 Coolant changed   
 Extinguisher checked   
 Extinguisher recharged   
 Microfilter changed

PADDOCK MOTORS  
 EXETER  
 BMW SPECIALIST  
 01404 851021

54759 miles

5/12/08 *[Signature]*

Date/Stamp/Signature

Brake fluid changed   
 Coolant changed   
 Extinguisher checked   
 Extinguisher recharged   
 Microfilter changed

Westerly No 16295  
 Barnstable

81750 miles

20-4-10 *[Signature]*

Date/Stamp/Signature

Brake fluid changed   
 Coolant changed   
 Extinguisher checked   
 Extinguisher recharged   
 Microfilter changed

Croyde Motors  
 Jones Hill  
 Croyde EX33 1LX  
 Tel: 01271 890260  
 Dealer 47.6LP  
 ID 6.05

MOT 12.01.06

Date/Stamp/Signature

Brake fluid changed   
 Coolant changed   
 Extinguisher checked   
 Extinguisher recharged   
 Microfilter changed

Westerly No 16295  
 Barnstable  
 BMW Service

64632 miles

30-3-11 *[Signature]*

Date/Stamp/Signature

Brake fluid changed   
 Coolant changed   
 Extinguisher checked   
 Extinguisher recharged   
 Microfilter changed

83399 miles

01/05/19 *[Signature]*

Date/Stamp/Signature

# H J WICKETT & Co

Central Garage, The Square, Bradworthy, Holsworthy, Devon EX22 7SZ  
Tel 01409 241 217 Fax 01409 241 021

Email [hjwickettandco@gmail.com](mailto:hjwickettandco@gmail.com) Website [www.hjwickett.co.uk](http://www.hjwickett.co.uk)

Registered Office: Central Garage, The Square, Bradworthy, Holsworthy, Devon, EX22 7SZ VAT Number 143897533

## INVOICE

Invoice Date  
01 Nov 2023

Invoice Number  
INV-39855

Account Number

Work Carried Out On BMW M3 M30 OAP

Description	Quantity	Unit Price	VAT	AmountGBP
Carry out MOT test	1.00	54.85	Zero Rated	54.85
			Subtotal	54.85
			Total Zero Rated	0.00
			Invoice Total GBP	54.85
			Total Net Payments GBP	0.00
			Amount Due GBP	54.85

Due Date: 30 Dec 2023

**Please Note :**

Wheel nuts and tyre pressures must be checked within 50 miles/ 24 Hours  
No Warranty given on polished finish alloy wheels

**Terms:**

30 Days Nett  
Payment by end of month during which invoice is received.  
Interest on Overdue accounts charged at a rate of 3% above the minimum lending rates.  
All Goods remain the Property of H J Wickett & Co until paid for in full  
To Pay via Internet or telephone banking please use the following bank details  
**Bank HSBC / Sort Code 40-24-25 / Bank Account Number 51000888**

pd Transfer  
15/2



# PADDOCK MOTORS BMW SPECIALIST

**Oaklands Garage Sidmouth Road EX5 2JJ**

01395 232049

DATE: 20/09/23  
INVOICE: 33183

BMW: E36 M3  
Reg: M3OAP  
Vin: WBSBK92020EX67218  
Mileage: 84522

	AMOUNT
Carried out engine oil service HIGH PERFORMANCE ENGINE OIL 10W60 5.5 LITRES OIL FILTER	£195.00
Carried out air con re-gas REFRIGERANT	£80.00
Environmental disposal	£4.90
Replaced front wiper blades FRONT WIPER SET	£24.00
*** PLEASE NOTE ***	
* Front tyres have approx 9mm tread wear remaining	
* Rear tyres have approx 9mm tread wear remaining	
* Front brake pads have approx 80% wear remaining (discs required when pads changed)	
* Rear brake pads have approx 50% wear remaining (discs required when pads changed)	
SUBTOTAL	£303.90
VAT @ 20%	£60.78
MOT	
<b>TOTAL</b>	<b>£364.68</b>

PAYMENT TERMS: PAYMENT IS DUE UPON RECEIPT OF THIS INVOICE E & OE

For bank payments: Natwest | Account: 5806 3064 | Sort Code: 53-50-55

The Paddock Garage Ltd trading as Paddock Motors  
Registered in England and Wales. Company Number 5711502 Oaklands Garage Sidmouth Road EX5 2JJ VAT No.879 6007 80



MOT TEST CENTRE & MOTOR ENGINEERS

# A&K GIFFORD

River Tamar Way  
Dobles Lane Industrial Estate  
Holsworthy  
Devon EX22 6HL  
t 01409 259 403

Invoice 1028330

Date: 05-05-2023 1 13 PM  
Job: J016660

No. SH024

**Vehicle**  
 Registration: M30AP Mileage: 84179  
 BMW 3 Series M3 1999 3.2 Petrol - BLACK VIN: WBSBK92020EX67218

**Issues and Work Description**  
 Work Description  
 To strip front calipers, clean pistons and cylinders. Refit and test. Reprogram key fobs.

**Work performed**

Parts					
Parts	Part No	Qty	Unit Price	VAT %	Net Total
Brake fluid dot 4	BRAKE FLUID 4	0.50	4.80	20.0	2.40
<b>Parts SubTotal</b>					<b>£2.40</b>

Labour			VAT %	Net Total
Labour	Labour charge		20.0	182.00
<b>Labour SubTotal</b>				<b>£182.00</b>

VAT				Labour	Net Total
VAT Code	Rate %	Net Total	VAT Total		
(1)	20.00	184.40	36.88	Parts	2.40
				VAT	36.88
<b>Invoice Total</b>					<b>£221.28</b>

Title to the goods supplied remain with this company until payment for them has been satisfactorily received - E & O E. Terms & Conditions available upon request

Bank Transfer.

PD 15<sup>5</sup> 23

VAT No. 313326790

Page 1 of 1

Wheels nuts/bolts are torqued to vehicle specification. We recommend they are checked after 50 miles.

All of our repairs are covered for 12 months/12,000 miles against mechanical failure (subject to inspection and confirmation by ourselves). Your statutory rights are not affected in any way



**Bank payments:**

Sort Code: 309491  
Account number: 00337622

Terms: Title of goods does not pass until payment for goods has been received in full. Non-payment of this invoice will result in interest and collection costs being added. Interest will be charged @ 5% monthly on amounts outstanding after 14 days from the date of invoice.

Class 4 & 7



Warranty Claim No.:  
N/A

Warranty Claim Branch:  
N/A

**CASH SALE INVOICE**

Invoice Name & Address

Customer Name & Address

You were served by:  
Adam Gazely

Date & Tax Point:  
20/06/2022

Reg No.:

Vehicle Description:

Chassis No.:

Mileage:

WIP No.:  
20016

Document No.:  
30074938

Account No.:  
C0002

Order No.:

Page No.:  
1

Part No.	Description	Bin Loc	Qty.	Unit Price	Total
Standard Parts P B34.35.2.227.385	052381/TEMP.SENS	N/STOCK	1	15.30 EACH 0.00	15.30
<b>Subtotal:</b>					<b>15.30</b>

**SPECIAL ORDERS  
ARE  
NON RETURNABLE**

V	Rate	Service/Goods	V.A.T.
S	20.00	15.30	3.06

<b>Parts Surcharge</b>	<b>15.30</b>
<b>Net</b>	<b>15.30</b>
<b>V.A.T.</b>	<b>3.06</b>
<b>Total</b>	<b>18.36</b>

E & O E

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail.barnstaple@westerlybmw.co.uk  
Internet www.westerlybmw.co.uk

Registered Office Helston Garages Ltd  
T/A Westerly Barnstaple  
85 Meneage Street, Helston  
Cornwall TR13 8RD  
Registered in England and Wales 703021  
VAT Registration No. 447 4166 38







MOT TEST CENTRE & MOTOR ENGINEERS

# A&K GIFFORD

River Tamar Way  
Dobles Lane Industrial Estate  
Holworthy  
Devon EX22 6HL

† 01409 259 403

## Invoice I026537

Date: 15-06-2022 11:42 AM  
Job: J015005

No. SH024

Vehicle  
Issues and Work  
Description

Registration: M3OAP  
BMW 3 Series M3 1999 3.2 Petrol - BLACK  
Mileage: 83969  
VIN: WBSBK92020EX67218

Work performed

Work Description  
To carry out a brake fluid change

### Parts

Parts	Part No	Qty	Unit Price	VAT %	Net Total
Brake fluid dot 4	BRAKE FLUID 4	0.75	6.45	20.0	4.84
<b>Parts SubTotal</b>					<b>£4.84</b>

### Labour

Labour	VAT %	Net Total
Labour charge	20.0	24.00
<b>Labour SubTotal</b>		<b>£24.00</b>

Invoice Total

VAT Code	Rate %	Net Total	VAT Total	Labour	Parts
(1)	20.00	28.84	5.77	24.00	4.84
<b>VAT</b>					<b>5.77</b>
<b>Invoice Total</b>					<b>£34.61</b>

pd Bank transfer  
18<sup>6</sup>22.

VAT No. 313326790

Page 1 of 1

Wheels nuts/bolts are torqued to vehicle specification. We recommend they are checked after 50 miles.

All of our repairs are covered for 12 months/12,000 miles against mechanical failure (subject to inspection and confirmation by ourselves). Your statutory rights are not affected in any way



### Bank payments:

Sort Code: 309491  
Account number: 00337622

Terms: Title of goods does not pass until payment for goods has been received in full. Non-payment of this invoice will result in interest and collection costs being added. Interest will be charged @ 5% monthly on amounts outstanding after 14 days from the date of invoice.

Class 4 & 7



# H J WICKETT & Co

Central Garage, The Square, Bradworthy, Holsworthy, Devon EX22 7SZ

Tel 01409 241 217 Fax 01409 241 021

Email [hjwickettandco@gmail.com](mailto:hjwickettandco@gmail.com) Website [www.hjwickett.co.uk](http://www.hjwickett.co.uk)

Registered Office: Central Garage, The Square, Bradworthy, Holsworthy, Devon, EX22 7SZ VAT Number 14897533

## INVOICE

**Invoice Date**

28 Oct 2021

**Invoice Number**

INV-28444

**Account Number**

**Work Carried Out On** BMW M3 OAP

Description	Quantity	Unit Price	VAT	AmountGBP
Carry out MOT test	1.00	54.85	No VAT	54.85
			Subtotal	54.85
			Total No VAT	0.00
			Invoice Total GBP	54.85
			Total Net Payments GBP	0.00
			<b>Amount Due GBP</b>	<b>54.85</b>

**Due Date: 30 Nov 2021**

**Please Note :**

Wheel nuts and tyre pressures must be checked within 50 miles/ 24 Hours  
No Warranty given on polished finish alloy wheels

**Terms:**

30 Days Nett  
Payment by end of month during which invoice is received.  
Interest on Overdue accounts charged at a rate of 3% above the minimum lending rates.  
All Goods remain the Property of H J Wickett & Co until paid for in full  
To Pay via Internet or telephone banking please use the following bank details  
**Bank HSBC / Sort Code 40-24-25 / Bank Account Number 51000888**

AD 18<sup>th</sup> 21

# ADVANCE TYRE SPECIALISTS LTD

4 & 5 RMD Units, Holsworthy Ind. Estate, Holsworthy, Devon EX22 6HL

Web: [advancetyresholsworthy.co.uk](http://advancetyresholsworthy.co.uk)

Tel: (01409) 254 446

Inv. Date: 23/06/2021

<< INVOICE AD0000062644 >>

Page: 1

C0013046AD

Registration : M3 OAP  
 Vehicle : BMW M3 F/SET  
 Mileage : 083730  
 Annual Miles :  
 Order Number :  
 Fitter : SAM  
 Sheet No. :

Payments: MASTERCARD (456.00)

ck Code	Description	Qty	Price	Total
DU24540YR17	245/40R17 DUNLOP SPMAXX RT2 95Y Fuel: C, Grip: A, Noise: 69dB,1	2.00	105.20	210.40
V	VALVE	2.00	0.00	0.00
B	WHEEL BALANCING	2.00	0.00	0.00
D	ENVIRONMENTAL TYRE DISPOSAL REARS	2.00	2.08	4.16
DU22545YR17	225/45R17 DUNLOP SPMAX RT2* 94W Fuel: C, Grip: A, Noise: 71dB,1	2.00	80.64	161.28
V	VALVE	2.00	0.00	0.00
B	WHEEL BALANCING	2.00	0.00	0.00
D	ENVIRONMENTAL TYRE DISPOSAL FRONTS	2.00	2.08	4.16

**\* PLEASE CHECK WHEEL TRIMS BEFORE LEAVING AND YOUR WHEEL NUTS AFTER 30 MILES \***  
**ALL GOODS REMAIN THE PROPERTY OF ADVANCE TYRES LTD UNTIL PAYMENT IN FULL**  
**THANKYOU FOR YOUR CUSTOM**

Total (Exc. VAT) 380.00  
 Total VAT 76.00  
 Total (Inc. VAT) 456.00  
 Total Paid 456.00  
 Invoice Balance 0.00

Brakes Exhausts Tracking Puncture Repairs 24 Hour Agricultural Breakdown Batteries

Registered Company No. 7635581 VAT Registration No. 792 8546 76



# H J WICKETT & Co

Central Garage, The Square, Bradworthy, Holsworthy, Devon EX22 7SZ

Tel 01409 241 217 Fax 01409 241 021

Email [hjwickettandco@gmail.com](mailto:hjwickettandco@gmail.com) Website [www.hjwickett.co.uk](http://www.hjwickett.co.uk)

Registered Office: Central Garage, The Square, Bradworthy, Holsworthy, Devon, EX22 7SZVAT Number143897533

## INVOICE

? Invoice Date  
17 May 2021

Invoice Number  
INV-26247

Account Number

Work Carried Out OnBMW M3 OAP

Description	Quantity	Unit Price	VAT	AmountGBP
83717 Miles Remove and replace all 4 rear Brake Hoses. Make up and fit 1 new brake pipe. Top up and bleed brakes.	1.00	171.50	20%	171.50
Check and replace brake light switch. Road Test				
Brake Hose	2.00	24.60	20%	49.20
Brake Hose	2.00	26.10	20%	52.20
Brake Pipe & Fittings	1.00	10.00	20%	10.00
Brake Fluid	1.00	6.00	20%	6.00
Brake Cleaner	1.00	2.00	20%	2.00
Brake Light Switch	1.00	19.49	20%	19.49
			Subtotal	310.39
			Total VAT 20%	62.08
			InvoiceTotal GBP	372.47
			Total Net Payments GBP	0.00
			Amount DueGBP	372.47

Due Date: 30 Jun 2021

**Please Note :**

Wheel nuts and tyre pressures must be checked within 50 miles/ 24 Hours  
No Warranty given on polished finish alloy wheels

**Terms:**

30 Days Nett  
Payment by end of month during which invoice is received.  
Interest on Overdue accounts charged at a rate of 3% above the minimum lending rates.  
All Goods remain the Property of H J Wickett & Co until paid for in full  
To Pay via Internet or telephone banking please use the following bank details  
**Bank HSBC / Sort Code 40-24-25 / Bank Account Number 51000888**

*Paid for  
Hub for o/c  
21.6.21*

# **PADDOCK MOTORS BMW SPECIALIST**

Oaklands Garage Sidmouth Road EX5 2JJ

01395 232049

DATE: 01/05/19  
INVOICE: 24156

INVOICE TO:

BMW: E36 M3 CONVERTIBLE  
Reg: M3OAP  
Vin: EX67218  
Mileage: 83399

	AMOUNT
Carried out MOT test – PASS – 441551079394 (Exp: 02/05/2020)	
Carried out brake fluid service DOT4FLUID	£50.00
*** PLEASE NOTE *** * Tyres wearing close to legal limit	
SUBTOTAL	£50.00
VAT @ 20%	£10.00
MOT	£54.85
<b>TOTAL</b>	<b>£114.85</b>

PAYMENT TERMS: PAYMENT IS DUE UPON RECEIPT OF THIS INVOICE E & OE

# PADDOCK MOTORS BMW SPECIALIST

**Oaklands Garage Sidmouth Road EX5 2JJ**

01395 232049

DATE: 04/05/18  
INVOICE: 22261

INVOICE TO:

BMW: E36 M3  
Reg: M3OAP  
Vin: EX67218  
Mileage: 82918

DESCRIPTION	AMOUNT
Courtesy Car A2GCU	£12.00
Carried out MOT test – PASS – 576829488230 (Exp: 02/05/2019)	
Carried out inspection 2 service	£430.00
ENGINE FLUSH	£10.00
FUEL FLUSH	£10.00
BMW HIGH PERFORMANCE ENGINE OIL 10W60 6.0 LITRES	
OIL FILTER	
AIR FILTER	
SPARK PLUG (x6)	
MICRO-FILTER	
CAM COVER GASKET	
DIFF OIL	
ATF GEARBOX OIL	
Replaced both rear shock absorber top mounts	£97.50
REAR SUSPENSION TOP MOUNT (x2)	£52.96
*** PLEASE NOTE ***	
* OSR, OSR & NSR tyres wearing close to limits	
* NSF tyre has approx 5mm tread wear remaining	
SUBTOTAL	£612.46
VAT @ 20%	£122.49
MOT	£54.85
<b>TOTAL</b>	<b>£789.80</b>
PAYMENT TERMS: PAYMENT IS DUE UPON RECEIPT OF THIS INVOICE E & OE	





MOT TEST CENTRE & MOTOR ENGINEERS

# A&K GIFFORD

River Tamar Way  
Dobles Lane Industrial Estate  
Holsworthy  
Devon EX22 6HL  
t 01409 259 403



## Invoice

Invoice No. 1015080  
Account Ref. SH024 Job No. J004442  
Date. 14/12/2016

### Labour

MOT Test class 4

	Qty	Unit	VAT%	Net Total
			0.0	45.00
<b>Sub Total</b>				<b>45.00</b>

*Paid 17/12/16*

Reg No.	M30AP
Make	BMW
Model	3 Series M3
VIN	WBSBK92020EX67218
Mileage	82758

VAT No. 313 3267 90

Net Total	45.00
VAT	0.00
<b>Invoice Total</b>	<b>45.00</b>

Title to the goods supplied remain with this company until payment for them has been satisfactorily received - E & O E.

All of our repairs are covered for 12 months/12,000 miles against mechanical failure (subject to inspection and confirmation by ourselves). Your statutory rights are not affected in any way



### Bank payments:

Sort Code: 309491  
Account number: 00337622

Terms: Title of goods does not pass until payment for goods has been received in full. Non-payment of this invoice will result in interest and collection costs being added. Interest will be charged @ 3% monthly on amounts outstanding after 14 days from the date of invoice.

Class 4, 5L & 7





**ACCOUNT INVOICE**

<b>Invoice Name &amp; Address</b>	<b>Customer Name &amp; Address</b>

<b>Order Number</b>	<b>You were served by:</b>	<b>Operator:</b>			
	Jayne Liston	JL			
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>	<b>Repair Date</b>		
F0008	40056568	20/04/2016	20/04/2016		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	81750	12:34	1	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSF No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	M3OAP	09/09/1999		W 63373	58392

	Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
A	0000249 BMW engine oil service			9.00	66.30	S
L	5555 Shell BMW LL04 0w-30 Recommended By BMW.			5.50	49.50	S
X	B11.42.7.833.769 Oil Filter M3	1@	13.19	1.31	11.88	S
X	B64.11.9.069.895 Micro Filter	1@	23.80	2.38	21.42	S
				<b>Sub-total</b>	<b>149.10</b>	
A	3400022 Replace fluid in ABS brake system			6.00	44.20	S
L	7771 Brake Fluid Change			1.00	9.00	S
				<b>Sub-total</b>	<b>53.20</b>	
A	6450509 Discharge & fill air condition			7.00	49.16	S
				<b>Sub-total</b>	<b>49.16</b>	
Z	VHCOSFTYRE worn on inner edge 225/45 R 17 91Y					
				<b>Sub-total</b>	<b>0.00</b>	
Z	VHCOSRTYRE 245/40 R 17 W					

© KERN/DAE

V	Rate	Service/Goods	V.A.T.

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office Helston Garages Ltd  
T/A Westerly Barnstaple  
85 Meneage Street, Helston  
Cornwall TR13 8RD  
England and Wales 703021  
447 4166 38

Registered in  
VAT Registration No.





**ACCOUNT INVOICE**

<b>Invoice Name &amp; Address</b>	<b>Customer Name &amp; Address</b>

<b>Order Number</b>	<b>You were served by:</b>	<b>Operator:</b>			
	<b>Jayne Liston</b>	<b>JL</b>			
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>	<b>Repair Date</b>		
F0008	40056568	20/04/2016	20/04/2016		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	81750	12:34	2	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSb No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	M3OAP	09/09/1999		W 63373	58392

Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
			Sub-total	0.00	
Z VHCNSRTYRE			Sub-total	0.00	
Z VHCNOTES n/s/r brake pipe clip broken			Sub-total	0.00	
Z VHCNOTES n/s/f brake pipe slightly corroded			Sub-total	0.00	

© HERRIDGE

<b>E &amp; O. E.</b>	<b>V</b>	<b>Rate</b>	<b>Service/Goods</b>	<b>V.A.T.</b>	<b>Net</b>	<b>251.46</b>
Parts	S	20.00	251.46	50.29	<b>V.A.T.</b>	<b>50.29</b>
Surcharge					<b>Total</b>	<b>301.75</b>
Labour					<b>Paid</b>	<b>0.00</b>
Sublet					<b>Owing</b>	<b>301.75</b>
Menus						

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office Helston Garages Ltd  
T/A Westerly Barnstaple  
85 Meneage Street, Helston  
Cornwall TR13 8RD  
England and Wales 703021  
447 4166 38

Registered in  
VAT Registration No.



Suspension - <i>Continued</i>		Repair Cost £	Status
Check NSF Suspension	<input checked="" type="checkbox"/>		
Check OSF Suspension	<input checked="" type="checkbox"/>		
Check NSR Suspension	<input checked="" type="checkbox"/>		
Check OSR suspension	<input checked="" type="checkbox"/>		
Drivetrain			
Check Engine	<input checked="" type="checkbox"/>		
Check Gearbox	<input checked="" type="checkbox"/>		
Check Differential	<input checked="" type="checkbox"/>		
Check Exhaust	<input checked="" type="checkbox"/>		
Check Driveshafts	<input checked="" type="checkbox"/>		
Bodywork			
Check Bodywork Area 1	<input type="checkbox"/> N/C		
Check Bodywork Area 2	<input type="checkbox"/> N/C		
Check Bodywork Area 3	<input type="checkbox"/> N/C		
Check Bodywork Area 4	<input type="checkbox"/> N/C		
Levels, Belts, Hoses & Battery			
Check Engine Oil Level	<input checked="" type="checkbox"/>		
Check Engine Coolant Level	<input checked="" type="checkbox"/>		
Check Brake Fluid Level	<input checked="" type="checkbox"/>		
Check Washer Fluids	<input checked="" type="checkbox"/>		
Check PAS Fluid	<input checked="" type="checkbox"/>		
Check Drive Belts	<input checked="" type="checkbox"/>		
Check Battery	<input checked="" type="checkbox"/>		
Check Hoses	<input checked="" type="checkbox"/>		
CBS Data			
Oil Service	<input type="checkbox"/> N/C		
Brake Fluid Service	<input type="checkbox"/> N/C		
Microfilter Service	<input type="checkbox"/> N/C		
Vehicle Check Service	<input type="checkbox"/> N/C		
Notes			
Add Notes (1)	<input type="checkbox"/>	n/s/r brake pipe clip broken	Call 01/06/16
Add Notes (2)	<input type="checkbox"/>	n/s/f brake pipe slightly corroded	Call 01/06/16
Add Notes (3)	<input type="checkbox"/> <input type="checkbox"/> N/C		
Citnow			
Video	<input type="checkbox"/> N/C		

NOTE: This report is the result of a visual examination only of those items listed. Further checks may be necessary to determine full extent of requirements.

DATA PROTECTION: The above named dealer or associated companies may wish to keep you informed about products, services and special offers

Please tick these boxes if the customer does not wish to receive further updates. By post [ ] By telephone [ ] By email [ ]

Service Advisor Signature:

Customer's Signature:

Please Note **THIS IS NOT AN INVOICE** (Prices are VAT inclusive and valid for 30days)

Date: 20.4.16

Address: Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone: 01271 325444  
Fax: 01271 322882  
e-mail: mail@westerlybarnstaple.bmw-net.co.uk  
Internet: www.westerlybmw.co.uk

Registered Office: Helston Garages Ltd  
T/A Westerly Barnstaple  
85 Meneage Street, Helston  
Cornwall TR13 8RD  
England and Wales 703021  
447 4166 38

Registered in  
VAT Registration No.



**CASH SALE INVOICE**

<b>Invoice Name &amp; Address</b>	<b>Customer Name &amp; Address</b>
. . . . .	. . . . .

<b>Order Number</b>	<b>You were served by:</b>	<b>Operator:</b>		
	Adrian Pickup	APP		
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>		
c4200040	42418606	02/03/2016		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>
		0	14:46	1
<b>Notes</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
			P 57691	0

Part No.	Description	Bin Loc.	Qty.	Unit Price	Unit Des.	Disc.	Net Total	V
P B83.21.2.365.924	Helix Ultra Raci	A2B	1	18.75	EACH K		15.00	S

E & O E	<b>V</b>	<b>Rate</b>	<b>Service/Goods</b>	<b>V.A.T.</b>	<b>Parts</b>	15.00
	S	20.00	15.00	3.00	Surcharge	0.00
					Discount	3.75
					Net	15.00
					V.A.T.	3.00
					Total	18.00
					Paid	
					Owing	

Address Clifton Moorgate  
Clifton Moor  
York YO30 4WR  
Telephone 01904 693313  
Fax 01904 693724  
e-mail mail@cooper.york.bmw-net.co.uk  
Internet www.cooper.york.bmw.co.uk

Registered Office The Cooper Group Limited  
Inchcape House  
Langford Lane, Kidlington  
Oxford OX5 1HT  
England & Wales 821770  
Registered in GB 243 6111 93  
VAT Registration No.





MOT TEST CENTRE & MOTOR ENGINEERS

# A&K GIFFORD

River Tamar Way  
Dobles Lane Industrial Estate  
Holtworthy  
Devon EX22 6HL  
t 01409 259 403

## Invoice

Page 1 of 1

Invoice No. I012646  
Account Ref. SH024 Job No. J007512  
Date. 12/01/2016

Labour	Qty	Unit	VAT%	Net Total
MOT Test class 4	1.00	45.00	- 0.0	45.00
<b>Labour Sub Total</b>				<b>45.00</b>

Reg No.	M3OAP
Make	BMW
Model	3 Series M3
VIN	WBSBK92020EX67218
Mileage	80504

VAT No. 313 3267 90

Net Total	45.00
VAT	0.00
<b>Invoice Total</b>	<b>45.00</b>

Title to the goods supplied remain with this company until payment for them has been satisfactorily received - E & O E.

All of our repairs are covered for 12 months/12,000 miles against mechanical failure (subject to inspection and confirmation by ourselves). Your statutory rights are not affected in any way



### Bank payments:

Sort Code: 309491  
Account number: 00337622

Terms: Title of goods does not pass until payment for goods has been received in full. Non-payment of this invoice will result in interest and collection costs being added. Interest will be charged @ 3% monthly on amounts outstanding after 14 days from the date of invoice.

Class 4, 5L & 7



# PADDOCK MOTORS BMW SPECIALIST

Oaklands Garage Sidmouth Road EX5 2JJ

01395 232049

DATE: 15/07/14  
INVOICE 13733

INVOICE TO:

FOR: BMW E36 M3 Conv  
Reg M3OAP  
Vin EX67218  
Mileage 76331

DESCRIPTION	AMOUNT
Courtesy Car	£12.00
To carry out a fixed price inspection 1 service with flushes	£355.00
6 Litres Castrol Oil	
1 x Oil Filter	
1 x Cam Cover Gasket Set	
1 x Forte Engine Flush	£10.00
1 x Forte Fuel Flush	£10.00
To remove and replace the clutch	£245.00
1 x Clutch Kit	£206.40
6 x 07.11.9.906.045 Clutch Bolt	£3.42
1 x 21.51.1.223.328 Ball Pin	£1.00
1 x 21.51.7.570.284 Spring Clip	£3.25
To remove and replace the rear exhaust brackets and rubber mounts	£35.00
2 x 18.20.1.402.479 Rear Exhaust Bracket	£20.00
2 x 18.21.1.723.410 Rear Exhaust Bracket Shackle	£12.58
2 x 18.20.1.401.797 Rear Exhaust Rubber Mount	£51.50
1 x Various Nuts & Bolts	£5.65
*****PLEASE NOTE*****	
NSF alloy wheel is slightly buckled	
Front metal brake pipes are slightly corroded	
SUBTOTAL	£970.80
VAT @ 20%	£194.16
MOT	
TOTAL	£1,164.96

PAYMENT TERMS: PAYMENT IS DUE UPON RECEIPT OF THIS INVOICE E & OE

# PADDOCK MOTORS BMW SPECIALIST

Oaklands Garage Sidmouth Road EX5 2JJ

01395 232049

DATE: 11/03/14  
INVOICE 12941

INVOICE TO:

FOR: BMW E36 M3 Conv  
Reg M3OAP  
Vin EX67218  
Mileage 75835

DESCRIPTION	AMOUNT
To remove and replace both rear lower ball joints, including new nuts and bolts	£105.00
2 x Rear Lower Ball Joint	£49.90
2 x 33.32.6.863.853 Eccentric Bolt	£10.76
2 x 33.32.1.094.653 Eccentric Washer	£2.34
2 x 33.32.6.760.668 Nut	£2.00
To carry out a full 4 wheel alignment and adjust as required	£95.00
SUBTOTAL	£265.00
VAT @ 20%	£53.00
MOT	£18.00
<b>TOTAL</b>	<b>£318.00</b>

PAYMENT TERMS: PAYMENT IS DUE UPON RECEIPT OF THIS INVOICE E & OE



# Measurement printout

Car standard measurement

Bosch © \* Bosch CCD 6R

M \* R+ \*\* OK \* BMW\_STANDARD / 34.00 / 265 / C

Date: 11.03.2014 13:45:25



# BOSCH

Version (program) v5.0b1510/v5.0b1508	Version (CCD) v5.0b2401	Version (target data) BMW v34.00	Serial number LA0002437	Last service 02.05.2013
------------------------------------------	----------------------------	-------------------------------------	----------------------------	----------------------------

**RIVERSIDE MOTORS**  
RIVERSIDE HOUSE  
EXETER ROAD  
OTTER ST MARY  
DEVON  
EX11 1NR  
01404 813016

## Customer

Company: PaddockMotors

## Vehicle

Registration: M3 OAP

## Vehicle:

**BMW v34.00**  
BMW \* 3-er E 36 \* M 3 \* 3,2

## Order

Ride height Rear Axle			Measurement Data			Target Data	
Ride height	left	right	+540.0 mm	+540.0 mm	-1.0 mm	[+540.0 mm]	+1.0 mm

Ride height Front Axle			Measurement Data			Target Data	
Ride height	left	right	+585.0 mm	+585.0 mm	-1.0 mm	[+585.0 mm]	+1.0 mm

Rear Axle		Initial Measurement	Target Data	Final Measurement
Camber	left	-0°25'	-0°30' [-1°45'] +0°30'	-1°58'
	right	-0°05'		-1°26'
Cross Camber		-0°20'	[0°15']	-0°32'
Individual Toe	left	-0°13'	-0°03' [+0°10'] +0°03'	+0°09'
	right	-0°09'		+0°08'
Total Toe		-0°23'	-0°05' [+0°20'] +0°05'	+0°17'
Geometrical driving axis		+0°02'	-0°03' [+0°00'] +0°03'	

Front Axle		Initial Measurement	Target Data	Final Measurement
Castor 20°	left	+7°16'	-0°30' [+7°50'] +0°30'	
	right	+8°03'		
Toe out on turns	left	-1°45'	-0°30' [-1°24'] +0°30'	
	right	-2°04'		
Camber	left	-0°38'	-0°30' [-0°46'] +0°30'	-0°39'
	right	-0°38'		-0°33'
Cross Camber		+0°00'	[0°30']	-0°07'
Individual Toe	left	+0°09'	-0°03' [+0°10'] +0°03'	+0°10'
	right	+0°09'		+0°08'
Total Toe		+0°18'	-0°05' [+0°20'] +0°05'	+0°18'
Setback		-0°09'	-0°10' [+0°00'] +0°10'	-0°08'

- Measurement was done in its design position.



# BRAKE TEST REPORT

**Customer:**  
**Car Make:** BMW  
**Car Model:** M3  
**Model Year:** 1999  
**License No:** M3OAP

**Total weight:** 1880 kg  
**Mileage:** 74955  
**Date:** 07/01/2014 10:22:24  
**Operator:**  
**Remarks:**

	Left	Right	Imb	Efficiency
<b>Service Brake Front</b>	274 kgf *	298 kgf *	11 %	
<b>Service Brake Rear</b>	235 kgf *	261 kgf *	5 %	
<b>Service Brake Total Forc</b>	1068 kgf			57 %
<b>Parking Brake</b>	213 kgf *	212 kgf *	%	
<b>Parking Brake Total Forc</b>	425 kgf			23 %

\* = lock

ATL, CI 4, PB Rear, Dual Line

	Front		Rear	
	Left	Right	Left	Right
<b>Bind</b>	✓	✓	✓	✓
<b>Judder</b>	✓	✓	✓	✓
<b>Grab</b>	✓	✓	✓	✓

\* = Problem

**Overall result**

Passed

# MOT Exhaust Emission Test Results

Basic Emission Test

Date: 07-01-2014 10:00:00

**A & K Gifford**

Dobles Lane Industrial Estate  
EX22 6HL Holsworthy

VTS: V 102886  
Phone: 01409 259403  
Fax: 01409 253188

## Vehicle Details

Vehicle Registration Number: M3OAP

Description	Unit	Limits Min.	Limits Max.	Actual Value	Result
<b>Fast Idle Test</b>					
Engine Speed	rpm	2500	3000	2800	Pass
CO	%		0.20	0.02	Pass
HC	ppm		200	71	Pass
Lambda		0.970	1.030	0.997	Pass
<b>Natural Idle Test</b>					
Engine Speed	rpm	450	1500	790	Pass
CO	%		0.30	0.01	Pass

## Overall Result

Exhaust Emissions Test  
Notes

PASSED

Engine temperature measurement by manual observation; Temperature gauge showed warm engine.

Tested By

DEAN

Signature

Software Version

DSS MOT-UK V2.1


## MOT STATION COPY ##



TFI Motor Trimmers  
 6 Cofton Units  
 Cofton Road  
 Marsh Barton  
 Exeter  
 EX2 8QW  
 VAT Reg No: 926 3436 20

TELEPHONE: 01392 498888

Invoice



<b>Document No</b>	4857
<b>Document Date</b>	19/11/2013
<b>Order No.</b>	
<b>Account Ref.</b>	SHAW2

Quantity	Details	Net Amount	VAT Rate	VAT
1.00	Strip Drivers seat back, replace complete outer bolster section leather panels	120.00	20.00	24.00
1.00	Leather Hide	100.00	20.00	20.00

RE-ORDER REF RS20

BMW M3  
 M3 OAP  
**If you are happy with our service, please tell a friend.**  
**If not, please tell us!**  
 TFI Motor Trimmers are members of Devon County Trading Standards BUY WITH CONFIDENCE SCHEME

<b>Total Net Amount</b>	220.00
<b>Total VAT Amount</b>	44.00
<b>Invoice Total</b>	264.00

## ACCOUNT INVOICE

Invoice Name & Address	Customer Name & Address

Order Number	You were served by:	Operator:			
	Jayne Liston	JL			
Account No.	Document Number	Date & Tax Point	Repair Date		
F0008	40043778	14/11/2013	14/11/2013		
Make & Model	Chassis No.	Mileage	Time	Page	
E36 M3 Convertible S	EX67218	74337	11:34	1	
Reference No.	Reg No.	Reg Date.	VSB No.	W.I.P. No.	Job No.
	M3OAP	09/09/1999		W 40731	45507

	Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
A	3400522 Replace ABS braking system hydraulic fluid			4.00	28.44	S
L	7771 Brake Fluid Change			1.00	9.95	S
Z	CONS Environmental Disposal Charge			6.50	6.50	S
				Sub-total	44.89	
A	3499000 Replace all 4 bleed nipples on brake calipers			12.00	85.32	S
X	B34.11.1.153.197 029067/VALVE	4@	4.92	0.98	18.70	S
				Sub-total	104.02	

E. & O. E.		V	Rate	Service/Goods	V.A.T.	Net	148.91
Parts	18.70	S	20.00	148.91	29.78	V.A.T.	29.78
Surcharge	0.00					Total	178.69
Labour	130.21					Paid	0.00
Sublet	0.00					Owing	178.69
Menus	0.00						

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office SMB (Barnstaple) Ltd  
T/A Westerly Barnstaple  
85 Menage Street, Helston  
Cornwall TR13 8RD  
England and Wales 2561237  
447 4166 38  
Registered in  
VAT Registration No.





**CASH SALE INVOICE**

<b>Invoice Name &amp; Address</b>	<b>Customer Name &amp; Address</b>

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		James Roberts		JR	
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>	<b>Repair Date</b>		
C0010	40090719	17/09/2012	17/09/2012		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	70588	15:12	1	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSB No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	M30AP	09/09/1999		W 32316	100926

	Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
D	000 Carry out full Oil Service and Safety Check			9.00	62.25	S
L	8883 Castrol TWS Motorsport oil 10W60			5.50	79.75	S
X	B11.42.7.833.769 E46 MB Oil Filter	1@	12.38	10.0	11.15	S
				Sub-total	153.15	
D	3131051 Replace both spring struts if required parts ordered cannot be sent back			25.00	172.92	S
X	M31.10.6.774.714 Self-Locking Hex Nu	2@	1.25	0.0	2.50	S
X	B31.31.2.228.007 FRONT LEFT SPRING S	1@	198.51	10.0	178.66	S
X	B31.31.2.228.008 FRONT RIGHT SPRING	1@	198.51	10.0	178.66	S
X	B31.32.1.129.977 SPACER UD-M	2@	3.75	0.0	7.50	S
X	B93.06.0.000.619 Large Cable Tie	1@	0.10	0.0	0.10	S
				Sub-total	540.34	
X	ZDEP 40090473 / Deposit	-1@	83.33	0.0	-83.33	S
				Sub-total	-83.33	
T	NOTES Both front wishbone rear bushes worn, estimate to replace £195 inc vat. slight oil leak from diff input seal, estimate to replace £305 inc vat. KDS £99.00 inc vat.			0.00	0.00	S

Feeling the heat? Why not take advantage of our Air Conditioning System Offer From £99 inc

V	Rate	Service/Goods	V.A.T.

Address Matford Park Road  
Marsh Barton, Exeter  
Devon EX2 8FD  
Telephone 01392 822555  
Fax 01392 822580  
e-mail mail@westerlyexeter.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office SMB (Exeter) Ltd  
T/A Westerly Exeter  
85 Meneage Street, Helston  
Cornwall TR13 8RD  
England and Wales 1223102  
447 4166 38

Registered in  
VAT Registration No.





**ESTIMATE**

Invoice Name & Address	Customer Name & Address

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		James Roberts		JR	
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>		<b>Repair Date</b>	
C0010	0	17/09/2012			
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	0	13:32	1	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSB No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	M3OAP	09/09/1999		W 32914	0

	Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
D	3112135 Replace rubber mounts of both control arms			20.00	138.33	S
M	B31.12.9.069.035 N/STOCK RUBBER BRG	1@	25.25	10.0	22.73 S	
				Sub-total	161.06	
D	3311011 Replace shaft seal for final drive input fla			33.00	228.25	S
M	B33.12.1.205.138 010801 LOCK PLATE	1@	1.64	0.0	1.64 S	
M	B33.12.1.213.949 010801 Diff Pinion	1@	26.42	10.0	23.78 S	
				Sub-total	253.67	
A	NEG Fixed Menu Price 3200630 Front & rear axle adjt (with 3200150/590) -K				99.00	S
A	3200150 Check suspension alignment-KDS					
				Sub-total	99.00	

Feeling the heat? Why not take advantage of our  
Air Conditioning System Offer From £99 inc

Parts	48.15	V	Rate	Service/Goods	V.A.T.	Net	497.23
Surcharge	0.00	S	20.00	414.73	82.95	V.A.T.	99.45
Labour	465.58	S	20.00	82.50	16.50	Total	596.68
Sublet	0.00					Paid	0.00
Menus	0.00					Owing	596.68

Address: Maford Park Road, March Barton, Exeter, Devon EX2 8LD  
 Telephone: 01392 822555  
 Fax: 01392 822580  
 e-mail: [car@westerly.co.uk](mailto:car@westerly.co.uk)  
 Internet: [www.westerly.co.uk](http://www.westerly.co.uk)

Registered Office: SMB (Exeter) Ltd, T/A Westerly Exeter, 85 Meneage Street, Helston, Cornwall TR13 8RD, England and Wales 1223102, 447 4166 38  
 Registered in VAT Register No.



**CASH SALE INVOICE**

Invoice Name & Address

Customer Name & Address

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		James Roberts		JR	
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>	<b>Repair Date</b>		
C0010	40090719	17/09/2012	17/09/2012		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	70588	15:12	2	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSF No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	M3OAP	09/09/1999		W 32316	100926

Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
Sub-total				0.00	
<p>Feeling the heat? Why not take advantage of our Air Conditioning System Offer From £99 inc</p>					

Parts	295.24	V	Rate	Service/Goods	V.A.T.	Net	610.16
Surcharge	0.00	S	20.00	610.16	122.03	V.A.T.	122.03
Labour	314.92					Total	732.19
Sublet	0.00					Paid	0.00
Menus	0.00					Owing	732.19

Address Matford Park Road  
Marsh Barton, Exeter  
Devon EX2 8FD  
Telephone 01392 822555  
Fax 01392 822580  
e-mail mail@westerlyexeter.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office SMB (Exeter) Ltd  
T/A Westerly Exeter  
85 Maneage Street, Helston  
Cornwall TR13 8RD  
England and Wales 1223102  
447 4166 38

Registered in  
VAT Registration No.



**CASH SALE INVOICE**

Invoice Name & Address	Customer Name & Address

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		Chris Sparey		CS	
<b>Account No.</b>		<b>Document Number</b>		<b>Date &amp; Tax Point</b>	
C0002		40090473		07/09/2012	
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	64632	17:18	1	
<b>Notes</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>	
	M3OAP	09/09/1999	W 32316	0	

Feeling the heat? Why not take advantage of our Air Conditioning System Offer From £99 inc

Part No.	Description	Bin Loc.	Qty.	Unit Price	Unit Des.	Disc.	Net Total	V
P ZDEP	Deposit Taken	N/STK	1	83.33	EACH	0.00	83.33	S
B31.31.2.228.008	FRONT RIGHT SPRING S		1	198.51	EACH		ON ORDER	
B31.31.2.228.007	FRONT LEFT SPRING ST		1	198.51	EACH		ON ORDER	
B31.32.1.129.977	SPACER UD-M		2	3.75	EACH		ON ORDER	

*Paid With  
THANKS  
£100.00  
Deposit.  
M.*

© KENNEDY

V	Rate	Service/Goods	V.A.T.	Parts	83.33
S	20.00	83.33	16.67	Surcharge	0.00
				Discount	0.00
				Net	83.33
				V.A.T.	16.67
				Total	100.00
				Paid	0.00
				Owing	100.00

Address Matford Park Road  
Marsh Barton, Exeter  
Devon EX2 8FD  
Telephone 01392 822555  
Fax 01392 822580  
e-mail mail@westerlyexeter.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office SMB (Exeter) Ltd  
T/A Westerly Exeter  
85 Meneage Street, Helston  
Cornwall TR13 8RD  
England and Wales 1223102  
Registered in 447 4166 38  
VAT Registration No.



A FAMILY BUSINESS

**CASH SALE INVOICE**

Invoice Name & Address
Parts Retail Cash Sales - York . . . . .

Customer Name & Address
Parts Retail Cash Sales - York . . . . .

<b>Order Number</b>	<b>You were served by:</b>	<b>Operator:</b>		
	Adrian Pickup	app		
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>		
C7201	72391187	21/12/2011		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>
		0	10:19	1
<b>Notes</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
			P 53155	0

BMW Lifestyle Collection Available  
At Cooper BMW Dont Forget Your Catalogue

Part No.	Description	Bin Loc.	Qty.	Unit Price	Unit Des.	Disc.	Net Total	V
P B83.12.2.232.310	EDGETWS REFILL	D1A	1	16.63	EACH	0.00	16.63	

E & O. E.	<b>V</b>	<b>Rate</b>	<b>Service/Goods</b>	<b>V.A.T.</b>	<b>Parts</b>	<b>16.63</b>
	S	20.00	16.63	3.33	Surcharge	0.00
					Discount	0.00
					Net	16.63
					V.A.T.	3.33
					Total	19.96
					Paid	0.00
					Owing	19.96

Address Clifton Moorgate  
Clifton Moor  
York YO30 4WR  
Telephone 01904 693313  
Fax 01904 693724  
e-mail mail@cooper.york.bmw-net.co.uk  
Internet www.cooper.york.bmw.co.uk

Registered Office The Cooper Group Limited  
Inchcape House  
Langford Lane, Kidlington  
Oxford OX5 1HT  
England & Wales 821770  
GB 243 6111 93  
Registered in  
VAT Registration No.



**CASH SALE INVOICE**

<b>Invoice Name &amp; Address</b>	<b>Customer Name &amp; Address</b>

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		Steve Whipp		SW	
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>	<b>Repair Date</b>		
C0002	40031384	06/04/2011	30/03/2011		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	64632	15:10	1	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSB No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	M3OAP	09/09/1999		W 16751	32938

	Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
A	5499000 Investigate the roof not opening fully			12.00	99.60	S
				<b>Sub-total</b>	99.60	
A	5434515 Replace linkage for soft top drive			6.00	49.80	S
X	B54.34.8.174.834 ROD ASSY	1@	89.21	0	89.21 S	
X	B54.34.8.174.835 ROD ASSY	1@	55.84	0	55.84 S	
X	C16117700959 BOLT	1@	0.92	0	0.92 S	
X	B54.34.8.201.103 BOLT	2@	1.77	0	3.54 S	
X	B54.34.8.174.836 WASHER	1@	3.34	0	3.34 S	
X	B54.31.8.163.052 BUSH	2@	1.90	0	3.80 S	
X	B31.35.1.128.229 WASHER	1@	3.13	0	3.13 S	
X	B07.11.9.900.698 BOLT	1@	0.75	0	0.75 S	
X	B07.12.9.934.329 CIRCLIP	1@	0.41	0	0.41 S	
X	B07.11.9.913.834 BOLT	1@	0.42	0	0.42 S	
X	B51.31.8.174.832 WASHER	2@	1.54	0	3.08 S	
				<b>Sub-total</b>	214.24	
A	5434502 Initialise EM softop			3.00	24.90	S
				<b>Sub-total</b>	24.90	

E & O.E.		<b>V</b>	<b>Rate</b>	<b>Service/Goods</b>	<b>V.A.T.</b>	<b>Net</b>	<b>338.74</b>
<b>Parts</b>	<b>164.44</b>	<b>S</b>	<b>20.00</b>	<b>338.74</b>	<b>67.75</b>	<b>V.A.T.</b>	<b>67.75</b>
<b>Surcharge</b>	<b>0.00</b>					<b>Total</b>	<b>406.49</b>
<b>Labour</b>	<b>174.30</b>					<b>Paid</b>	<b>0.00</b>
<b>Sublet</b>	<b>0.00</b>					<b>Owing</b>	<b>406.49</b>
<b>Menus</b>	<b>0.00</b>						

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office SMB (Barnstaple) Ltd  
T/A Westerly Barnstaple  
85 Meneage Street, Helston  
Cornwall TR13 8RD,  
England and Wales 2561237  
447 4166 38

Registered in  
VAT Registration No.



**CASH SALE INVOICE**

<b>Invoice Name &amp; Address</b>	<b>Customer Name &amp; Address</b>

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		Steve White		SWI	
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>	<b>Repair Date</b>		
C0002	40031270	30/03/2011	30/03/2011		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	64632	15:50	1	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSB No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	M3OAP	09/09/1999		W 16751	32938

	Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
A	3400022			6.00	49.80	S
	Replace fluid in ABS brake system					
L	7771			1.00	9.95	S
	Brake Fluid Change					
Z	CONS			6.50	6.50	S
	Environmental Disposal Charge					
				<b>Sub-total</b>	<b>66.25</b>	

E. & O. E.		<b>V</b>	<b>Rate</b>	<b>Service/Goods</b>	<b>V.A.T.</b>	<b>Net</b>	<b>66.25</b>
<b>Parts</b>	<b>0.00</b>	<b>S</b>	<b>20.00</b>	<b>66.25</b>	<b>13.25</b>	<b>V.A.T.</b>	<b>13.25</b>
<b>Surcharge</b>	<b>0.00</b>					<b>Total</b>	<b>79.50</b>
<b>Labour</b>	<b>66.25</b>					<b>Paid</b>	<b>0.00</b>
<b>Sublet</b>	<b>0.00</b>					<b>Owing</b>	<b>79.50</b>
<b>Menus</b>	<b>0.00</b>						

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office SMB (Barnstaple) Ltd  
T/A Westerly Barnstaple  
85 Meneage Street, Helston  
Cornwall TR13 8RD.  
Registered in England and Wales 2561237  
VAT Registration No. 447 4166 38



**CASH SALE INVOICE**

<b>Invoice Name &amp; Address</b>	<b>Customer Name &amp; Address</b>

<b>Order Number</b>	<b>You were served by:</b>	<b>Operator:</b>		
	Dave Coleman	DC		
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>		
C0001	30027028	03/11/2010		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>
		0	16:33	1
<b>Notes</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
			P 13515	0

	Part No.	Description	Bin Loc.	Qty.	Unit Price	Unit Des.	Disc.	Net Total	V
P	B83.12.0.411.413	Leather Care	BMWDIS	1	12.72	EACH	0.00	12.72	S
P	B51.91.0.302.070	ST-carbons.	N/STOC	1	18.72	EACH	0.67	18.72	S

Paid Card  
3/10/10

E & O. E.	<b>V</b>	<b>Rate</b>	<b>Service/Goods</b>	<b>V.A.T.</b>	<b>Parts</b>	<b>31.44</b>
	S	17.50	31.44	5.50	Surcharge	0.00
					Discount	0.00
					Net	31.44
					V.A.T.	5.50
					Total	36.94
					Paid	0.00
					Owing	36.94

Address: Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone: 01271 325444  
Fax: 01271 322882  
e-mail: mail@westerlybarnstaple.bmw-net.co.uk  
Internet: www.westerlybmw.co.uk

Registered Office: SMB (Barnstaple) Ltd  
T/A Westerly Barnstaple  
85 Meneage Street, Helston  
Cornwall TR13 8RD.  
Registered in England and Wales 2561237  
VAT Registration No. 447 4166 38







# PADDOCK MOTORS [EXETER LTD] BMW SPECIALIST

**Fenny Bridges EX14 3BG**

01404 851021

DATE: 26/07/10  
INVOICE 5512

INVOICE TO:

FOR: BMW E36 M3 Conv.  
Reg M3OAP  
Vin EX67218  
Mileage 63054

DESCRIPTION	AMOUNT
Courtesy Car	£10.00
Carry out inspection II	£415.00
1x oil filter	
1x air filter	
1x cam cover gasket set	
6x spark plugs	
6 litres fully synthetic motor oil	
2.5 litres gearbox oil	
1 litre LSD diff oil	
Replace corroded rear brake pipes	£250.00
Brake pipe	£15.00
Please note; Rear brake pads and discs 75% worn	
Supply only top up engine oil	£10.00
SUBTOTAL	£700.00
VAT @ 17.5%	£122.50
MOT	
<b>TOTAL</b>	<b>£822.50</b>

PAYMENT TERMS: PAYMENT IS DUE UPON RECEIPT OF THIS INVOICE E & OE



\*\*\*\* INVOICE \*\*\*\*

Stephenson Street  
 Gladstone Industrial Estate  
 Thornaby, Cleveland. TS17 6AL  
 Tel: 01642 617626 Fax: 01642 678610  
 www.teessideautotech.co.uk  
 VAT Registration No. 317 5102 88



CASH SALE

Job No JOB NO.:	:	N/A
NUMBER:		023444
DATE/TAX POINT:		10/07/10
ORDER NO:		N/A
A/C REF.:		CASH

PARTS

1.00 10W/60TWS                      TWS 10W/60 M3 OIL                      @    12.72                      12.72

Reg No :  
 Make :  
 Mileage :  
 Chass No :  
 Notes 1 :  
 Notes 2 :

VATABLE ITEMS	12.72
TOTAL VAT	2.23
SUB TOTAL	14.95
ZERO RATED	0.00
INVOICE TOTAL	14.95

>> THIS CASH SALE IS DUE FOR PAYMENT <<

**CASH SALE INVOICE**

<b>Invoice Name &amp; Address</b>	<b>Customer Name &amp; Address</b>

<b>Order Number</b>	<b>You were served by:</b>	<b>Operator:</b>		
	Michael Davidson	MD		
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>		
C0001	30025052	24/05/2010		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>
E36 M3 Convertible S	EX67218	0	10:01	1
<b>Notes</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	M3OAP	09/09/1999	P 64352	0

	Part No.	Description	Bin Loc.	Qty.	Unit Price	Unit Des.	Disc.	Net Total	V
P	B61.31.8.360.417	Stop Light Switc	B07041	1	18.47	EACH	0.00	18.47	S
P	ZDEL	county delivery	N/STK	1	2.50	EACH	1.50	2.50	S

D. E.	<b>V</b>	<b>Rate</b>	<b>Service/Goods</b>	<b>V.A.T.</b>	<b>Parts</b>	<b>20.97</b>
	<b>S</b>	17.50	20.97	3.67	<b>Surcharge</b>	0.00
					<b>Discount</b>	0.00
					<b>Net</b>	20.97
					<b>V.A.T.</b>	3.67
					<b>Total</b>	24.64
					<b>Paid</b>	0.00
					<b>Owing</b>	24.64

Address Howard Avenue  
 Barnstaple  
 Devon EX32 8QA  
 Telephone 01271 325444  
 Fax 01271 325444  
 e-mail mail@westl...nstaple.bmw-net.co.uk  
 Internet www.westerlybnw.co.uk

Registered Office SMB (Barnstaple) Ltd  
 T/A Westerly Barnstaple  
 85 Meneage Street, Helston  
 Cornwall TR13 8RD.  
 England and Wales 2561237  
 447 4166 38

Registered in  
 VAT Registration No.



# Holsworthy Motor Company

M.O.T.s • SERVICING • REPAIRS

Neet House, Neet Way, Holsworthy Industrial Estate,

Holsworthy. Devon. EX22 6ES

----- Tel: (01409) 254 545 -----

Invoice No :

**3393**

Invoice / Tax Date: 08-Jan-10

V.A.T.Reg No 980 8775 64

TEL NO : 254551

Quantity	Item	Net Price	
		each	total
	Vehicle : BMW M3		
	Reg No: M3 OAP		
	Mileage :		
	TO CARRY OUT M.O.T. & REPAIRS		
	TO REMOVE BOTH REAR WHEELS , STRIP OUT HANDBRAKE		
	SHOES & REPLACE WITH NEW.		
	RE-ADJUST HANDBRAKE CABLE RE-ASSEMBLE & ROAD		
	TEST		
	LABOUR		£40.00
	HANDBRAKE SHOES		£25.76
	SUNDRIES		£1.15
	Applicable only with an MOT		£45.00
	Sub total excluding MOT		£66.91
	VAT @ 15%		£11.71
	Invoice Total		£123.62

**RECEIVED WITH THANKS**

Thank you for your custom



**CASH SALE INVOICE**

Invoice Name & Address

Customer Name & Address

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		Dave Coleman		DC	
<b>Account No.</b>		<b>Document Number</b>		<b>Date &amp; Tax Point</b>	
C0001		30021562		15/07/2009	
<b>Make &amp; Model</b>		<b>Chassis No.</b>		<b>Mileage</b>	
E36 M3 Convertible S		EX67218		0	
				<b>Time</b>	
				08:22	
				<b>Page</b>	
				1	
<b>Notes</b>		<b>Reg No.</b>		<b>Reg Date.</b>	
		M3OAP		09/09/1999	
				<b>W.I.P. No.</b>	
				P 56643	
				<b>Job No.</b>	
				0	

	Part No.	Description	Bin Loc.	Qty.	Unit Price	Unit Des.	Disc.	Net Total	V
P	ZDEP	30021543 / DEPOS	N/STK	-1	2.40	EACH	0.00	-2.40	S
P	B51.25.8.171.800	STOPPER	N/STOC	1	2.40	EACH	0.00	2.40	S

E. & O. E.

V	Rate	Service/Goods	V.A.T.		
				<b>Parts</b>	0.00
				<b>Surcharge</b>	0.00
				<b>Discount</b>	0.00
				<b>Net</b>	0.00
				<b>V.A.T.</b>	0.00
				<b>Total</b>	0.00
				<b>Paid</b>	0.00
				<b>Owing</b>	0.00

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office SMB (Barnstaple) Ltd  
T/A Westerly Barnstaple  
Matford Park Road, Marsh Barton  
Exeter EX2 8FD  
England 2561237  
VAT Registration No. 447 4166 38

**CASH SALE INVOICE**

<b>Invoice Name &amp; Address</b>	<b>Customer Name &amp; Address</b>

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		Dave Coleman		DC	
<b>Account No.</b>		<b>Document Number</b>		<b>Date &amp; Tax Point</b>	
C0001		30021543		13/07/2009	
<b>Make &amp; Model</b>		<b>Chassis No.</b>		<b>Mileage</b>	
E36 M3 Convertible S		EX67218		0	
				<b>Time</b>	
				14:19	
				<b>Page</b>	
				1	
<b>Notes</b>		<b>Reg No.</b>		<b>Reg Date.</b>	
		M3OAP		09/09/1999	
				<b>W.I.P. No.</b>	
				P 56643	
				<b>Job No.</b>	
				0	

Part No.	Description	Bin Loc.	Qty.	Unit Price	Unit Des.	Disc.	Net Total	V
P B51.41.1.973.500	Clip	B06033	2	0.14	EACH	0.00	0.28	S
P ZDEP	DEPOSIT TAKEN	N/STK	1	2.40	EACH	0.00	2.40	S
B51.25.8.171.800	STOPPER		1	2.40	EACH		ON ORDER	

Paid Cash  
13-07-09



E. & O. E.	<b>V</b>	<b>Rate</b>	<b>Service/Goods</b>	<b>V.A.T.</b>	<b>Parts</b>	
	S	15.00	2.68	0.40	Surcharge	2.68
					Discount	0.00
					Net	2.68
					V.A.T.	0.40
					Total	3.08
					Paid	0.00
					Owing	3.08

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office SMB (Barnstaple) Ltd  
T/A Westerly Barnstaple  
Matford Park Road, Marsh Barton  
Exeter EX2 8FD  
England 2561237  
VAT Registration No. 447 4166 38

**CASH SALE INVOICE**

Invoice Name & Address	ISS

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		Terry Skipper		TS	
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>	<b>Repair Date</b>		
C0002	40022287	11/05/2009	11/05/2009		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	56932	15:19	1	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSB No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	M3OAP	09/09/1999		W 54953	24103

	Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
A	LAB Investigate aircon not working correctly...checked no gas in system.			9.00	71.10	S
L	Re-charged Air con system & carried out function t 9998 Air Conditioning Refrigerant			1.00	15.00	S

E & O.E.		<b>V</b>	<b>Rate</b>	<b>Service/Goods</b>	<b>V.A.T.</b>		
Parts	0.00	S	15.00	86.10	12.92		Net 86.10
Surcharge	0.00						V.A.T. 12.92
Labour	86.10						Total 99.02
Sublet	0.00						Paid 0.00
Menus	0.00						Owing 99.02

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office SMB (Barnstaple) Ltd  
T/A Westerly Barnstaple  
Matford Park Road, Marsh Barton  
Exeter EX2 8FD  
England 2561237  
447 4166 38  
Registered in  
VAT Registration No.





## Paddock Motors Exeter Ltd Independent BMW Specialist

**Fenny Bridges**

EX14 3BG

01404 851021

DATE: 5-Dec-2008

INVOICE 0196

INVOICE TO:

FOR: BMW E36 M3

Reg M30AP

Vin EX67218

Mileage 54753

DESCRIPTION	AMOUNT
Courtesy car	£10.00
To carry out fixed cost oil service	£130.00
1 X Oil filter	
6.5 Litres oil	
Adjust handbrake	
1 X Brake fluid change	£40.00
Check for fault reverse light and PDC not working	
Trace fault to the reverse light switch. Replaced	£25.00
1 X Reverse light switch	£5.37
Replace the n/s mirror glass and repair wiring in o/s mirror	£25.00
1 X Mirror glass 51.16.2.267.223	£60.85
To replace the n/s track rod end and both rear mounts	£125.00
1 X Track rod and washers	£63.95
2 X Mountings	£31.84
SUBTOTAL	£517.01
VAT	£77.55
MOT	
TOTAL	£594.56

PAYMENT TERMS: PAYMENT IS DUE UPON RECEIPT OF THIS INVOICE E & OE

# MOBILE WINDSCREENS

ST. PHILIPS ROAD  
BRISTOL BS2 0HL  
TEL: (0117) 3042000  
FAX: (0117) 3042009  
VAT No. 303 1517 13



**National Windcreens**  
The National Consortium

CHECKED BY	
INVOICE NUMBER	1875228
INVOICE DATE	130608
DATE OF DAMAGE	100608
REASON FOR REPLACEMENT	CRACKED

INVOICE TO:

NAME & ADDRESS JOB COMPLETED AT:

ORD POL	
------------	--

PROD. CODE		EXCESS		SUPPLY & FIT		Price	
WET	DRY	BASE	MOBILE	REG. NUMBER	M3 OAP	REPAIR	Disc %
MW BRANCH: 21-14		MANUFACTURER/MODEL		BMW 3SER COU.		FIT ONLY	Nett Price
ENGINEER: 1020		MILEAGE		53239		TIME COMPLETED	*11.40
SUNDRIES 2432							
PLEASE PRINT DRIVER'S NAME:		COMPANY NAME DIVISION:		WINDSCREEN	HEATED REAR	BODY GLASS	
PRIMER DATE & BATCH		PRIMER DATE & BATCH		URETHANE DATE & BATCH	21 11 08	Sub Total	
		UKL550247		UKB1950247		VAT	
PRE - INSTALLATION CHECK/COMMENTS:						Total	
						Less Excess	60.00
						Total	60.00
						E & OE	

\*FOR YOUR OWN SAFETY. This vehicle should NOT be moved before the time shown here: TIME: 12.40  
Only applies in cases of direct glazed products/services. If the vehicle is driven away before time shown, it is at the owners/driver's own risk.

TERMS: Payment is due immediately unless credit facilities have been agreed. ANY DISCOUNT ALLOWED WILL BE FORFEITED AND CHARGED IF THIS INVOICE IS NOT PAID IN FULL WITHIN THE AGREED PAYMENT TERMS WHICH ARE 30 DAYS FROM THE MONTH END FOLLOWING THE INVOICE DATE.

I agree the work above has been completed and accept responsibility for payment within the terms and conditions shown above and under the Conditions of Sale, as set out on the reverse of this invoice.

1 AM/AM NOT REGISTERED FOR VAT (Delete as appropriate)

CUSTOMER NAME (PRINTED) SHAW

SIGNATURE:

REF: MWINV/303

SALES INVOICE. REMITTANCE ADVICE TO BE SENT WITH PAYMENT TO: MOBILE WINDSCREENS LTD

Vat Invoice No	
Upgrading Invoice No	
Excess Invoice No	
Direct Bill No	592750

INVOICE NUMBER	1875228
INVOICE DATE	130608
<b>METHOD OF PAYMENT</b>	
A/C NO.	
CASH	CHEQUE <input type="checkbox"/> CREDIT CARD <input checked="" type="checkbox"/>
CHQ. GTE. CARD No.	

PAYMENT RECD. BY \_\_\_\_\_

**CASH SALE INVOICE**

<b>Invoice Name &amp; Address</b>	<b>Customer Name &amp; Address</b>

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		Dave Coleman		DC	
<b>Account No.</b>		<b>Document Number</b>		<b>Date &amp; Tax Point</b>	
C0001		30015267		23/01/2008	
<b>Make &amp; Model</b>		<b>Chassis No.</b>		<b>Mileage</b>	
				0	
				10:36	
				1	
<b>Notes</b>		<b>Reg No.</b>		<b>Reg Date.</b>	
				W.I.P. No.	
				P 42963	
				Job No.	
				0	

	Part No.	Description	Bin Loc.	Qty.	Unit Price	Unit Des.	Disc.	Net Total	V
P	B07.11.9.919.801	BOLT	N/STOC	4	0.25	EACH	0.00	1.00	S
P	B07.11.9.931.087	WASHER	N/STOC	4	0.34	EACH	0.00	1.36	S

Paid Cash  
23-01-08

E. & O. E.	<b>V</b>	<b>Rate</b>	<b>Service/Goods</b>	<b>V.A.T.</b>	<b>Parts</b>	<b>2.36</b>
	<b>S</b>	17.50	2.36	0.41	<b>Surcharge</b>	0.00
					<b>Discount</b>	0.00
					<b>Net</b>	2.36
					<b>V.A.T.</b>	0.41
					<b>Total</b>	2.77
					<b>Paid</b>	0.00
					<b>Owing</b>	2.77

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office SMB (Barnstaple) Ltd  
T/A Westerly Barnstaple  
Matford Park Road, Marsh Barton  
Exeter EX2 8FD  
England 2561237  
447 4166 38

Registered in  
VAT Registration No.



**THE PADDOCK GARAGE LTD**  
INDEPENDENT BMW SPECIALIST

**DATE:** September 11, 2007  
**INVOICE** 1077

**FOR:** BMW E36 M3 Evo  
Reg M3 OAP  
Vin EX67218  
Mileage 48834

DESCRIPTION	AMOUNT
Replace flexi clutch hose for modified unit	£35.00
x Clutch hose kit.	£52.16
<b>SUBTOTAL</b>	
	£ 87.16
<b>VAT</b>	
	£ 15.25
<b>Less Excess</b>	
<b>TOTAL</b>	
	£ 102.41

VAT No. 879 6007 80

01404 823 408 / 07780 900347

T: 01404 823 408 / 07780 900347

E: INFO:THEPADDOCKGARAGE.CO.UK

W: WWW.THEPADDOCKGARAGE.CO.UK

A: MILESTONE BUSINESS PK, LONDON RD, WHIMPLE, EXETER, EX5 2QB  
Registered in England and Wales. Company Number 5711502 18 Newport Street, Tiverton EX16 6NL



**ACCOUNT INVOICE**

<b>Invoice Name &amp; Address</b>	<b>Customer Name &amp; Address</b>

<b>Order Number</b>	<b>You were served by:</b>	<b>Operator:</b>			
	<b>Dave Stacey</b>	<b>DS</b>			
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>	<b>Repair Date</b>		
<b>F0008</b>	<b>40013850</b>	<b>25/06/2007</b>	<b>18/06/2007</b>		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
<b>E36 M3 Convertible S</b>	<b>EX67218</b>	<b>47546</b>	<b>13:36</b>	<b>1</b>	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSB No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	<b>M3OAP</b>	<b>09/09/1999</b>		<b>W 37344</b>	<b>14679</b>

	Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
A	0000221 BMW Inspection I (including body insp)			54.00	362.07	S
X	B11.42.7.833.769 Oil Filter M3	1@	8.81	0	7.93	S
X	B81.22.9.407.103 Plastilube	1@	0.59	0	0.57	S
X	B83.12.0.404.498 SCREEN WASH	1@	1.71	0	1.54	S
X	B91.35.0.000.019 TWS REFILL	2@	13.18	3	23.07	S
X	ZOTOIL4 Tws Motorsport 4lt	1@	42.55	0	42.55	S
				<b>Sub-total</b>	<b>437.73</b>	
A	0012520 Replace coolant (with an Inspection)			9.00	60.35	S
X	B17.11.1.719.384 Radiator Drain Plug	1@	3.41	0	3.07	S
X	B81.22.9.407.454 Antifreeze	2@	6.80	1	11.90	S
				<b>Sub-total</b>	<b>75.32</b>	
X	B51.71.1.960.752 Support Lifting Pla	3@	2.60	0	7.02	S
				<b>Sub-total</b>	<b>7.02</b>	
X	B51.48.1.905.599 Rivet	2@	0.22	0	0.42	S
				<b>Sub-total</b>	<b>0.42</b>	
T	NOTE Rear brake discs & pads below min thickness o/s/f & n/s/r tyres below min tread o/s/r tyre on min tread Slight play in n/s track rod end			0.00	0.00	O

E & O.E.	<b>V</b>	<b>Rate</b>	<b>Service/Goods</b>	<b>V.A.T.</b>

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office SMB (Barnstaple) Ltd  
T/A Westerly Barnstaple  
Matford Park Road, Marsh Barton  
Exeter EX2 8FD  
England 2561237  
447 4166 38  
Registered in  
VAT Registration No.

*attended to.*

## ACCOUNT INVOICE

Invoice Name & Address	Customer Name & Address

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		Dave Stacey		DS	
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>	<b>Repair Date</b>		
F0008	40013850	25/06/2007	18/06/2007		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	47546	13:36	2	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSB No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	M3OAP	09/09/1999		W 37344	14679

Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
n/s semi-trailing arm bush separating Brake fluid service due 09/07					
Sub-total				0.00	

E & O.E.	<b>V</b>	<b>Rate</b>	<b>Service/Goods</b>	<b>V.A.T.</b>		
<b>Parts</b>	<b>S</b>	98.07	17.50	520.49	91.09	<b>Net</b> 520.49
<b>Surcharge</b>		0.00				<b>V.A.T.</b> 91.09
<b>Labour</b>		422.42				<b>Total</b> 611.58
<b>Sublet</b>		0.00				<b>Paid</b> 0.00
<b>Menus</b>		0.00				<b>Owing</b> 611.58

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office SMB (Barnstaple) Ltd  
T/A Westerly Barnstaple  
Matford Park Road, Marsh Barton  
Exeter EX2 8FD  
England 2561237  
447 4166 38  
Registered in  
VAT Registration No.

# Inspection Sheet 1999 Model Year



R.O. No. 37344  
 Reg. No. M3 OAP

## PRIOR TO COMMENCING THIS INSPECTION

Check for any outstanding quality enhancements using the service viewdata facility and complete as necessary. (Costs incurred should be claimed via the instructions for the specific action and are not included in the time allowance for this inspection).

FOR ALL MECHANICAL CHECKS (EG. BRAKES, SUSPENSION JOINTS) ALWAYS REFER TO T.I.S. REPAIR MANUAL

Check each item in turn and when completed mark in the box provided as follows:-

- OK. Item completed and in order. Corrected as necessary
- Item requires attention.

\*to be charged as an additional item

### Running-in Inspection at 1200 miles

	316i comp. from 1/99	316i-328i, ti	318tds - 325td	325tds	M3	Z3, 1.8 - 2.8	Z3, 1.9	M roadster, Coupé	316i - 328i	320d	520i - 540i	525td - 525tds	530d	M5	728i - 740i	750i	725tds	730d, 740d	840ci	
				E36					E46			E39					E38			
Call up Faults, print off and attach to inspection sheet																				
Change the engine oil and filter element																				
Change the oil in the manual gearbox																				
Change the oil in the rear axle final drive																				
<b>Final Check (Test Drive)</b>																				
Brakes, steering																				
Telltale and warning lights, Check - Control																				

### Oil Service

Replace fire extinguisher cartridge annually\* (Except Gloria type FIG34B must be replaced every 2 years. See date code on bottle)

Call up Faults, print off and attach to inspection sheet																					
Change the engine oil and filter element																					
Reset Service Interval Indicator																					
Check fluid level and concentration of screen wash reservoir including intensive wash fluid																					
Check brake and clutch fluid level																					
Check PAS system for leaks																					
Check steering for freedom from play																					
Check condition of track rod and front axle ball joints																					
Check steering box for leaks, UJ's couplings and flexible gaiters																					
Check braking system for leaks, damage, and correct position including handbrake cables and bleed nipple covers																					
Check brake pads/discs																					
Front and rear brake pads: measure thickness with gauge. If pads are renewed: Clean out caliper cavities, check brake disc thickness and surface condition, grease centering spigot on alloy wheels. If rear pads are renewed: check and clean parking brake linings.																					
Disc brake pads front and (if fitted) rear: remove and install, check overall thickness Clean out caliper cavities. Renew pads if necessary Brake discs: check surface condition and thickness including parking brakes Alloy wheels: grease centering spigots																					
Check hand brake lever travel, freedom of movement of cables and if necessary adjust as specified																					
Complete tyre check on page 2																					
Check and adjust screen washer jets																					
Check ALL exterior lights																					
Check ALL instrument and control lighting and ALL other interior courtesy lighting																					
Heating/Airconditioning: Renew Micro-filter/Active charcoal filter *(E36 - charge as additional item)																					
Check condition/operation of seatbelts																					
Final Check (Test Drive) Check: brakes, steering, clutch or automatic transmission, telltale and warning lights and Check Control.																					
Ensure Handbook Service Record is completed																					

### Inspection 1


Replace fire extinguisher cartridge annually\* (Except Gloria type FIG34B must be replaced every 2 years. See date code on bottle)

Check ALL exterior lights

## CASH SALE INVOICE

Invoice Name & Address	Customer Name & Address

Order Number	You were served by:	Operator:		
	Dave Coleman	DC		
Account No.	Document Number	Date & Tax Point		
C0001	30009859	11/11/2006		
Make & Model	Chassis No.	Mileage	Time	Page
E36 M3 Convertible S	EX67218	0	12:35	1
Notes	Reg No.	Reg Date.	W.I.P. No.	Job No.
	V272FLE	09/09/1999	P 31640	0

Part No.	Description	Bin Loc.	Qty.	Unit Price	Unit Des.	Disc.	Net Total	V
P B61.13.8.353.797	Bulb Socket With	B09041	1	3.37	EACH	0.00	3.37	S
<p><i>Paid Card</i></p> <p><i>11-11-06</i></p> 								

E. & O. E.

V	Rate	Service/Goods	V.A.T.	Parts	
S	17.50	3.37	0.59	Surcharge	3.37
				Discount	0.00
				Net	3.37
				V.A.T.	0.59
				Total	3.96
				Paid	0.00
				Owing	3.96

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office SMB (Barnstaple) Ltd  
T/A Westerly Barnstaple  
Matford Park Road, Marsh Barton  
Exeter EX2 8FD  
England 1223102  
447 4166 38



Authorised Workshop

**Westerly  
Barnstaple**

**BMW Service**

Part No 65 81 8 357 684

415.00 + VAT

11 10 - CONDENSOR: 269.29 → VAT ; £ 337  
64 53 9 713 678

*(Signature)*

**CASH SALE INVOICE**

<b>Invoice Name &amp; Address</b>	<b>Customer Name &amp; Address</b>

<b>Order Number</b>	<b>You were served by:</b>	<b>Operator:</b>			
	Dave Stacey	DS			
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>	<b>Repair Date</b>		
F0008	40011032	31/10/2006	31/10/2006		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	42463 <del>45992</del>	16:57	1	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSF No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	V272FLE	09/09/1999		W 30211	10964

	Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
A	6411586 Replace resistor for heater blower			3.00	20.12	S
X	B64.11.6.929.540 Switch	1@	71.92	7	64.73 S	
				Sub-total	84.85	
A	6453551 Remove and install or replace condenser of air conditioner			13.00	78.46	S
X	B64.50.8.374.959 Gasket Ring	2@	1.19	0	2.15 S	
X	B64.50.8.390.602 Gasket Ring	1@	0.64	0	0.58 S	
X	B64.50.8.390.603 Gasket Ring	1@	0.64	0	0.58 S	
X	B64.53.8.378.613 CONDENSOR	1@	288.51	28	259.66 S	
				Sub-total	341.43	
A	6453647			9.00	0.00	S
A	6453704 Replace both lines from evaporator to compressor or drier			5.00	30.18	S
X	B64.53.8.377.689 HOSE	1@	134.47	6	127.75 S	
X	B64.53.8.391.431 PRESS.HOSE	1@	69.37	3	65.91 S	
				Sub-total	223.84	
A	6450520 Discharging, evacuating and filling air			10.00	60.35	S
				Sub-total	60.35	

E.&O.E.		V.	Rate	Service/Goods	V.A.T.	Net	
Parts	521.36	S	17.50	710.47	124.33	710.47	
Surcharge	0.00					124.33	
Labour	189.11					834.80	
Sublet	0.00					0.00	
Menus	0.00					834.80	
						Owing	834.80

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office

SMB (Barnstaple) Ltd  
T/A Westerly Barnstaple  
Matford Park Road, Barnstaple  
Exeter EX2 8FD  
England T223102  
447 4166 38

Received with thanks

Signed: *(Signature)* Date: 31.10.06

# ADVANCE TYRE SPECIALISTS

Proprietor: Dave Edgcombe V.A.T. No. 792 8546 76

4 & 5 RMD Units, Holsworthy Ind. Estate, Holsworthy, Devon EX22 6HL

Brakes Exhausts Tracking Puncture Repairs

24 Hour Agricultural Breakdown Batteries

Tel: (01409) 254 446

Date: 13/09/2006

<< INVOICE HO018762 >>

Page: 1

CASH SALES

Invoice Date : 13/09/2006  
Registration :  
Vehicle : LOOSE WHEEL  
Mileage :  
Annual Miles :  
Order Number :  
Fitter : JAMES KYPRIANOU  
Sheet No. :

Payments: VISA CRED. (10.00)

Stock Code	Description	Qty	Price	Total
RE	RE-SEAL PLEASE CHECK WHEEL TRIMS BEFORE LEAVING AND YOUR WHEEL NUTS AFTER 30 MILES.	1.00	8.51	8.51

Total (Exc. VAT)	8.51
Total VAT	1.49
Total (Inc. VAT)	10.00
Total Paid	10.00
Amount Outstanding	0.00

All goods remain the property of Advance until payment is received in full.

## ACCOUNT INVOICE

Invoice Name & Address

Customer Name & Address

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		Steve Whipp		SW	
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>	<b>Repair Date</b>		
F0008	40010333	06/09/2006	05/09/2006		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	41338	14:09	1	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSB No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	V272FLE	09/09/1999		W 29686	10793

	Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
A	6317510 Remove and install or replace left or right fog lamp insert			1.00	6.71	S
X	B07.11.9.907.943 Screw	1@	0.12	0	0.11	S
X	B63.17.8.357.394 Supporting Frame Fo	1@	13.02	1	11.72	S
				<b>Sub-total</b>	<b>18.54</b>	
A	5133000 Remove and install left or right front door electric window regulator			9.00	60.35	S
X	B51.11.1.977.108 SUPPORT	1@	0.77	0	0.68	S
X	B51.32.1.938.884 Window Slider E36	2@	1.28	0	2.31	S
				<b>Sub-total</b>	<b>63.34</b>	
A	5499000 Lubricate all roof and window seals to stop squeak noise			4.00	26.82	S
				<b>Sub-total</b>	<b>26.82</b>	

E. & O. E.		<b>V</b>	<b>Rate</b>	<b>Service/Goods</b>	<b>V.A.T.</b>	<b>Net</b>	<b>108.70</b>
<b>Parts</b>	<b>14.82</b>	<b>B</b>	<b>17.50</b>	<b>108.70</b>	<b>19.02</b>	<b>V.A.T.</b>	<b>19.02</b>
<b>Surcharge</b>	<b>0.00</b>					<b>Total</b>	<b>127.72</b>
<b>Labour</b>	<b>93.88</b>					<b>Paid</b>	<b>0.00</b>
<b>Sublet</b>	<b>0.00</b>					<b>Owing</b>	<b>127.72</b>
<b>Menus</b>	<b>0.00</b>						

Address	Howard Avenue Barnstaple Devon EX32 8QA	Registered Office	SMB (Barnstaple) Ltd T/A Westerly Barnstaple Matford Park Road, Marsh Barton Exeter EX2 8FD England 1223102 447 4166 38
Telephone	01271 325444	Registered In	
Fax	01271 322882	VAT Registration No.	
e-mail	mail@westerlybarnstaple.bmw-net.co.uk		
Internet	www.westerlybmw.co.uk		

## CASH SALE INVOICE

<b>Invoice Name &amp; Address</b>	<b>Customer Name &amp; Address</b>

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		Steve Whipp		SW	
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>	<b>Repair Date</b>		
C0002	40009934	07/08/2006	07/08/2006		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	39903	12:22	1	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSB No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	V272FLE	09/09/1999		W 29019	10359

	Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
A	0000249 BMW engine oil service			9.00	67.05	S
L	8883 TWS Motor Sport Oil			5.50	71.23	S
X	B11.42.7.833.769 Oil Filter M3	1@	8.53	0	8.53	S
X	B83.12.0.404.498 SCREEN WASH	1@	1.71	0	1.71	S
				<b>Sub-total</b>	<b>148.52</b>	
-----						
A	3410014 Adjust parking brake			6.00	44.70	S
				<b>Sub-total</b>	<b>44.70</b>	
-----						
	NOTE * * * P L E A S E N O T E * * * Both front windows are making noise requires window regulators to be re-aligned Foglamp bracket broken Front Brake disc below min thickness Coolant change overdue			0.00	0.00	O
				<b>Sub-total</b>	<b>0.00</b>	
-----						
T	NOTE * * * P L E A S E N O T E * * * Suspect puncture in n/s/r tyre- Pressure low O/s/f tyre tread low Ac belt starting to crack			0.00	0.00	O

E & O.E.	V	Rate	Service/Goods	V.A.T.	

Address    Howard Avenue Barnstaple Devon EX32 8QA Telephone 01271 325444 Fax        01271 322882 e-mail    mail@westerlybarnstaple.bmw-net.co.uk Internet  www.westerlybmw.co.uk	Registered Office    SMB (Barnstaple) Ltd T/A Westerly Barnstaple Matford Park Road, Marsh Barton Exeter EX2 8FD England 1223102 447 4166 38	Registered In VAT Registration No.
-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------



## CASH SALE INVOICE

Invoice Name & Address

Customer Name & Address

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		Steve Whipp		SW	
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>	<b>Repair Date</b>		
C0002	40009934	07/08/2006	07/08/2006		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	39903	12:22	2	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSF No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	V272FLE	09/09/1999		W 29019	10359

Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
			Sub-total	0.00	

E & O. E.		V	Rate	Service/Goods	V.A.T.	Net	
Parts	10.24	S	17.50	193.22	33.81	193.22	
Surcharge	0.00					33.81	
Labour	182.98					227.03	
Sublet	0.00					0.00	
Menus	0.00					227.03	
						<b>Total</b>	<b>227.03</b>
						<b>Paid</b>	<b>0.00</b>
						<b>Owing</b>	<b>227.03</b>

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mall@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office SMB (Barnstaple) Ltd  
T/A Westerly Barnstaple  
Matford Park Road, Marsh Barton  
Exeter EX2 8FD  
England 1223102  
VAT Registration No. 447 4166 38





R.O. No. **29019**  
 Reg. No. **V272 FLE**

- OK. Item completed and in order.  
Corrected as necessary.
- Item requires attention.

\* to be charged as an additional item.

**BMW Inspection 1** – (Continued from page 1)

316i comp. from 1/99	316i-328i, ti	318tds-325td	325tds	M3	Z3, 1.8-2.8	Z3, 1.9	M Roadster, Coupé	316i-328i	320d	520i-540i	525td-525tds	530d	M5	728i-740i	750i	725tds	730d-740d	840ci
			<b>E36</b>					<b>E46</b>			<b>E39</b>					<b>E38</b>		

Body and underfloor: mark all corrosion and damage (not including body cavities) on illustration.

Comments

Inspection results shown by appropriate symbol:  
 Stone damage     Dents     Scratches/body damage  
 Underseal treatment

Call up faults, print off and attach to inspection sheet.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Change the engine oil and filter element.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Renew spark plugs.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Check valve clearances and adjust if necessary.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Empty water trap.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Check coolant level: including concentration and top up if necessary (-27°C to -43°C) <b>Important:</b> coolant must be renewed (no later than years stated, item charged additionally).	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Reset the Service Interval Indicator according to manufacturer's directives.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Windscreen washer and intensive cleaning system: check fluid level and top up if necessary.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Power steering: check oil level and top up if necessary.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Power steering: inspect for leaks.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Brake and clutch hydraulic system: check fluid level and top up if necessary.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Renew brake fluid as shown on the Service Interval Indicator, or at the latest after the number of years indicated.	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	
Front and rear brake pads: measure thickness with gauge. If pads are renewed: * Clean out calliper cavities, check brake disc thickness and surface condition, grease centering spigot on alloy wheels. If rear pads are renewed: Check parking brake linings.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Disc brake pads front and (if fitted) rear: remove and install, check overall thickness. Clean out calliper cavities, renew pads if necessary. Brake discs: check surface condition and thickness including parking brakes. Alloy wheels: grease centering spigots.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Check steering for freedom from play. Track rods, axle joints, steering box, gaiters, joint disc: check condition.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Underbody including all visible parts: check for damage, leakage and corrosion.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Brake system connections and lines: inspect for leakage, damage, and correct location.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Parking brake: Check travel and adjust according to instructions if necessary.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
<b>Tyres:</b> check and enter (including spare wheel). Tread depth (min MOT requirement 1.6mm in a continuous band comprising the central three-quarters of tread width and round the entire circumference) If wear is uneven recommend a wheel alignment check *	FL	FR	RL	RR	S															
	6 mm	2.5 mm	7 mm	7 mm	6.5 mm															
Tyre condition. Check for any cuts, lumps, bulges, or other damage.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>															
Tread pattern (pass or fail).	P#	P#	P#	P#	P#															
Correct tyre pressure spare wheel: max load +0.3 bar (ie. max. occupants + luggage) <b>except Spacesaver.</b> Complete and fit tyre pressure sticker	2.3 bar	2.3 bar	2.4 bar	2.4 bar	3.6 bar															
<b>Final Check</b> (test drive). Brakes (including bedding down of parking brake linings on cars with rear disc brakes), steering, clutch or automatic transmission, springs and shock absorbers (visual check), telltale and warning lights and Check Control.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Ensure Handbook Service Record is completed	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Inspection II**

Includes all items listed for inspection 1, plus the following additional checks and maintenance work.

Renew spark plugs.

Intake air silencer: renew element.

(If a fairly large amount of dust collects, reduce the interval as appropriate).







**BLACKCIRCLES**

Blackcircles Ltd, Cavalry park, Kings Meadows Road, Peebles EH45 9BU

## Sales Receipt

Number: **BC091589** Date: **26/06/2006**

Mileage 38827

Product Description	Quantity	Unit Price	Total
Michelin Pilot Sport 2 245/40 R17 Y	1	£130.64	£130.64
		<b>Subtotal:</b>	<b>£130.64</b>
		<b>VAT:</b>	<b>£22.86</b>
		<b>Total:</b>	<b>£153.50</b>

off side-rear

Refer a friend



3 x friends = £15

Go to your private area at [www.blackcircles.com](http://www.blackcircles.com) to see how close you are to receiving your £15



Money off next time

Thanks for your order!

Go to your private area at [www.blackcircles.com](http://www.blackcircles.com) to see what discounts are available to you.

Staff and Company Scheme



Call **0845 200 0022**

If you are part of or have a company that may benefit from our business scheme

You can now collect



**THE AirMiles TRAVEL COMPANY**

with every order.

**Thank you for your business**

Trading terms and conditions can be found online at [www.blackcircles.com](http://www.blackcircles.com)

Vat Number: 797182479 - registered in Scotland: SC224310

The AirMiles Travel Company is the trading name of AirMiles Travel Promotions Ltd



## ACCOUNT INVOICE

Invoice Name & Address	Customer Name & Address

Order Number		You were served by:		Operator:	
		Dave Stacey		DS	
Account No.	Document Number	Date & Tax Point	Repair Date		
F0008	40009135	06/06/2006	06/06/2006		
Make & Model	Chassis No.	Mileage	Time	Page	
E36 M3 Convertible S	EX67218	38413	14:36	1	
Reference No.	Reg No.	Reg Date.	VSB No.	W.I.P. No.	Job No.
	V272FLE	09/09/1999		W 27290	9466

	Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
A	5133020 Remove and install or replace left or right front electric window motor			10.00	67.05	S
X	B51.32.1.938.884 Window Slider E36	2@	1.28	0	2.31	S
X	B51.33.8.163.351 Bush	1@	0.43	0	0.39	S
X	B51.33.8.163.352 BUSH	1@	0.43	0	0.39	S
X	B67.62.8.360.978 Window Motor	1@	107.24	10	96.52	S
				Sub-total	166.66	
A	LAB r & i front bumper . replace auxillary cooling fan . recover / evacuate & recharge air con system .			20.00	134.10	S
X	B64.54.8.391.317 INLET FRAME	1@	188.94	9	179.50	S
				Sub-total	313.60	
A	a110 Air conditioning check (Special Offer)			6.00	46.79	S
L	a111 Air Conditioning Refridgerant			1.00	5.00	S
				Sub-total	51.79	
X	B92.93.0.000.001 Alarm Battery	1@	1.83	0	1.65	S
				Sub-total	1.65	

E. & O. E.		V	Rate	Service/Goods	V.A.T.	Net	533.70
Parts	280.76	S	17.50	533.70	93.40	V.A.T.	93.40
Surcharge	0.00					Total	627.10
Labour	252.94					Paid	0.00
Sublet	0.00					Owing	627.10
Menus	0.00						

Address Howard Avenue  
Barnstaple  
Devon EX32 8QA  
Telephone 01271 325444  
Fax 01271 322882  
e-mail mail@westerlybarnstaple.bmw-net.co.uk  
Internet www.westerlybmw.co.uk

Registered Office  
Registered in  
VAT Registration No.

SMB (Barnstaple) Ltd  
T/A Westerly Barnstaple  
Matford Park Road, Marsh Barton  
Exeter EX2 8FD  
England 1223102  
447 4166 38

## ACCOUNT INVOICE

<b>Invoice Name &amp; Address</b>	<b>Customer Name &amp; Address</b>

<b>Order Number</b>		<b>You were served by:</b>		<b>Operator:</b>	
		Dave Stacey		DS	
<b>Account No.</b>	<b>Document Number</b>	<b>Date &amp; Tax Point</b>	<b>Repair Date</b>		
F0008	40008976	24/05/2006	24/05/2006		
<b>Make &amp; Model</b>	<b>Chassis No.</b>	<b>Mileage</b>	<b>Time</b>	<b>Page</b>	
E36 M3 Convertible S	EX67218	37864	11:48	1	
<b>Reference No.</b>	<b>Reg No.</b>	<b>Reg Date.</b>	<b>VSF No.</b>	<b>W.I.P. No.</b>	<b>Job No.</b>
	M11XCD	09/09/1999		W 27138	9376

	Description of Goods / Services	Qty.	Unit Price	AW	Net Total	V
A	6121512 Replace battery			2.00	13.41	S
X	B61.21.8.381.741    006114/Battery	1@	65.00	6	58.50	S

E. & O. E.		<b>V</b>	<b>Rate</b>	<b>Service/Goods</b>	<b>V.A.T.</b>	<b>Net</b>	<b>71.91</b>
<b>Parts</b>	58.50	S	17.50	71.91	12.58	<b>V.A.T.</b>	<b>12.58</b>
<b>Surcharge</b>	0.00					<b>Total</b>	<b>84.49</b>
<b>Labour</b>	13.41					<b>Paid</b>	<b>0.00</b>
<b>Sublet</b>	0.00					<b>Owing</b>	<b>84.49</b>
<b>Menus</b>	0.00						

Address    Howard Avenue Barnstaple Devon EX32 8QA Telephone    01271 325444 Fax    01271 322882 e-mail    mail@westerlybarnstaple.bmw-net.co.uk Internet    www.westerlybmw.co.uk	Registered Office    SMB (Barnstaple) Ltd T/A Westerly Barnstaple Matford Park Road, Marsh Barton Exeter EX2 8FD England T223102 447 4166 38	Registered in VAT Registration No.
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------